

Incident report HF-2026-031

On 14 August 2026 at 02:10 the Rotterdam depot lost power for 42 minutes. Eleven reefer containers rose above 5 °C. The backup generator failed to start because its fuel filter was clogged. Corrective action: fuel filters on every depot generator are replaced every 90 days, and the generator is test-started every Monday at 09:00.