





CrackWatch test chart v1 (E2/E4). PRINT AT 100%.

Bar widths in mm above each bar. Check: ruler = 100 mm



Verify printed widths with a loupe/scanner before using as ground truth.