
# Module 13 error C110300 audi presense

Error on AUDI A6 C8 pressense. Error C110300


ODIS E

Go to:

13 module: ADAPTATION – (najdi bol spodaj) horizontal in vertical daj na 0.00




Nato pobriši DTC v DEVELOPMENT MODE




Confidential C

# Module 13 error C110300 audi presense




Confidential C

# Module 13 error C110300 audi presense

```
0790 - Sensor for Automatic Distance Regulation; Incorrectly Positioned
          C1103 00 [00001001] - -
          [FAULT_MISALIGNMENT_HORIZONTAL]
          Confirmed - Tested Since Memory Clear
             Freeze Frame:
                    Fault Priority: 4
                    Fault Frequency: 1
                    Reset counter: 143
                    Mileage: 183778 km
                    Date: 2025.04.08
                    Time: 22:29:23

                    Control Module temperature: 28 °C
                    Voltage terminal 15: 12.1 V
                    Velocity_vehicle_reference: 0.00 m/s
                    Longitudinal_acceleration_vehicle_reference: 0.00 m/s²
                    Status_ACC_System: ACC_Off Close Switch_Off
```

```
0791 - Sensor for Automatic Distance Regulation; Incorrectly Positioned
          C1103 00 [00001001] - -
          [FAULT_MISALIGNMENT_VERTICAL]
          Confirmed - Tested Since Memory Clear
             Freeze Frame:
                    Fault Priority: 4
                    Fault Frequency: 1
                    Reset counter: 143
                    Mileage: 183778 km
                    Date: 2025.04.08
                    Time: 22:29:23

                    Control Module temperature: 28 °C
                    Voltage terminal 15: 12.1 V
                    Velocity_vehicle_reference: 0.00 m/s
                    Longitudinal_acceleration_vehicle_reference: 0.00 m/s²
                    Status_ACC_System: ACC_Off_MainSwitch_Off
```

```
--------------------------------------------------------------------------------
Address 13: Auto Dist. Reg (J428)       Labels:| 5Q0-907-572-V2.clb
  Part No SW: 5Q0 907 572 H    HW: 5Q0 907 572 H
  Component: ACC BOSCH MQB H10 0620
  Dataset Number: V03935253UC 0205
  Coding: 3500478101FFC428949C810520301600000000000000000000
  Shop #: WSC 00066 790 00195
  ASAM Dataset: EV_ACCBOSCHVW416 002005
  ROD: EV_ACCBOSCHVW416_002_VW37.rod
  VCID: 3C2A47CFC6E5718A93F-8068

3 Faults Found:
9267 - Sensor for Automatic Distance Regulation; Incorrectly Positioned
         C1103 00 [00001001] - -
         [FAULT_ALIGNMENT_NOT_OK]
         Confirmed - Tested Since Memory Clear
            Freeze Frame:
                   Fault Priority: 4
                   Fault Frequency: 4
                   Reset counter: 149
                   Mileage: 183778 km
```

Confidential C