LAB 1 MIPS Instruction

Larry Delgado CECS341 Section 11

Convert these hexadecimal machine coded MIPS instructions to MIPS MARS assembly language. Answers expressed in binary or decimal or octal will be wrong.

Label: ADDRESS	Hexadecimal Machine Code	MIPS Instruction (use labels where applicable)
LN1: 0x0040 0100	0x000d6202	srl \$t2,\$t5, 8;
AGAIN: 0x0040 0104	0x01364820	add \$t1, \$t1, \$s6;
LN2: 0x0040 0108	0x15150003	bne \$t0, \$s5, 3; 0x0003
LN3: 0x0040 010c	0x08100049	j 0x100049
LN4: 0x0040 0110	0x8d280014	lw \$t0, 0x0014, \$t1;
LN5: 0x0040 0114	0x00134880	sll \$t1, \$s3, 2;
LN6: 0x0040 0118	0xad150190	sw \$s5 0x0190 \$t0;
NEXT: 0x0040 011c	0х0160с02а	slt \$t8,\$t3, \$zero;
LN7: 0x0040 0120	0x22730001	addi \$s3, \$s3;
END: 0x0040 0124	0x08100040	j 0x0100040;

## **DELIVERABLES:**

Submit your Lab1 Assignment to Beacboard by due date. Note that the filename should be in this format Lab3\_<student\_id>\_<lastname>

## Notes:

- This is an NOT a group assignment
- Keep these lab files as they will be needed for future labs!

Created by Tom Johnson, update by Gayathri Venna and Dr. Jelena Trajkovic (Spring 2021)