
- Engine - Motronic Multiport Fuel Injection (MF

ay 2002

onal Fuse, Relay, Control Module and Connector locations \Rightarrow Co




eshooting Procedures ⇒ Guided Fault Finding using VAS 5051/5 Relay location o

relay panel:


Relay panel:


2 J52 - Lo


4 J17 - Fu





97-39914







































211 212 213 214 215 216 217 218 219 220 221 222 223 224 97-35111



97-35112

