

Republic of the Philippines Department of Environment and Natural Resources

ENVIRONMENTAL MANAGEMENT BUREAU

Region VIII

DENR Compound, Jones St. Brgy. 02, Tacloban City Tel No. (053) 832-1088

MEMORANDUM

June 27, 2022

ENVIRONMENTAL MANAGEMENT BUMBAU a

RELEASED BY

DATE:_

WME: 8:29am

FOR

WILLIAM P. CUÑADO

Director

Environmental Management Bureau DENR Compound, Visayas Avenue

Diliman, Quezon City

Attention

Environmental Quality Division

Water Quality Management Section

Planning, Planning, and Program Development Division

FROM

The Regional Director

EMB Region VIII

SUBJECT

Accomplishment Report for the Waterbodies Monitored for the 2nd

Quarter CY 2022

Please find the attached Accomplishment Report of the four (4) waterbodies monitored in Region VIII for the 2nd Quarter CY 2022 namely; Matlang Bay, Camotes Sea, Dupong Bay and Ormoc Bay.

All monitored parameters like pH, temperature (°C), total suspended solids (mg/L), Oil and grease (mg/L), dissolved oxygen (mg/L), and heavy metals (Cu, As, Cd, Hg, Pb, and Cr⁺⁶) are within the standards set in the Water Quality Guidelines.

For his information.

REYNALDO B. BARRA, PME

		2ND QUAR	RTER CO	ASTAL MONITORING OF DUPONG BAY, MATLA	ING BAY, CA	MOTES SEA	AND ORMO	C BAY	
	т		150 00	CY 2022					2077
egion	Waterbody	Parameter	Stn. No.	Stn. ID		Average	Min	Max	Criterion
				Matlang & Dupong Bays & Camotes Sea, Isabel, Le	eyte Class SC	(11 Stations)			
				04/28/2022					
VIII	Dupon Bay		4	10°54'35"N, 124"26'05"E/Kinatumyan	8.11				
	Dupon Bay		2	10°54'56"N, 124"24'0"E/Sacay Point	8.05	8.04		Variables	
	Dupon Bay		3	10°54'50"N, 124°23'5"E/Buenavista	8.03		7.98	8.11	
	Dupon Bay		4	10°53'34.4"N, 124°25'43.7"E/Libertad	7.98				
	Camotes Sea	1	5	10°53'11"N, 124°26'04"E/Libertad	7.59	7.59	7.59	7.59	1616.866
	Matlang Bay	pH mg/L	6	10°53'13.7"N, 124°26'30.1"E/Libertad	8.07	7.82			6.5-8.5
	Matlang Bay	1	7	10°53'18"N, 124°26'46"E,Brgy. Libertad	7.99		6.75		
	Matlang Bay		8	10"53'42"N, 124*26'58"E/Sitio Pingag	6.75			8.07	
	Matlang Bay		9	10°53'08"N, 124°26'27"E/Matlang	8.06				
	Matlang Bay		10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	8.02				
	Matlang Bay		11	10°52'13"N, 124°28'13"E/Tolingon	8.01				
	Dupon Bay		1	10°54'35"N, 124°26'05"E/Kinatumyan	30	29.95	29.7		
	Dupon Bay		2	10°54'56"N, 124°24'0"E/Sacay Point	29.7			31.1	
	Dupon Bay		3	10"54'50"N, 124"23'5"E/Buenavista	29.7				
	Dupon Bay		4	10°53'34.4"N, 124°25'43.7"E/Libertad	30.4				
	Camotes Sea		5	10"53'11"N, 124°26'04"E/Libertad	31.1	31.1	31.1	31.1	
	Matlang Bay	Temp. ⁰ C	6	10"53'13.7"N, 124"26'30.1"E/Libertad	29.6	29.98	29.4		25-31
	Matlang Bay	1	7	10"53'18"N, 124"26'46"E,Brgy. Libertad	30.1				
	Matlang Bay]	8	10"53'42"N, 124"26'58"E/Sitio Pingag	29.7			31.5	
	Matlang Bay		9	10"53'08"N, 124°26'27"E/Matlang	29.6				
	Matlang Bay		10	10"52'55"N, 124°27'52"E/Brgy. Bilwang	29.4				
	Matlang Bay		11	10°52'13"N, 124°28'13"E/Tolingon	31.5				
	Dupon Bay		(1)	10°54'35"N, 124°26'05"E/Kinatumyan	<2.5	0.7			
	Dupon Bay	1	2	10"54'56"N, 124"24'0"E/Sacay Point	<2.5				
	Dupon Bay		3	10"54'50"N, 124"23'5"E/Buenavista	<2.5		<2.5	2.8	
	Dupon Bay	1	4	10°53'34.4"N, 124°25'43.7"E/Libertad	2.8				
	Camotes Sea	TSS mg/L	5	10°53'11"N, 124°26'04"E/Libertad	8,2	8.2	8.2	8.2	

Matlang Bay		6	10"53'13.7"N, 124"26'30.1"E/Libertad	<2.5		<2.5		80
Matlang Bay		7	10"53'18"N, 124°26'46"E,Brgy. Libertad	7.1				
Matlang Bay		8	10°53'42"N, 124°26'58"E/Sitio Pingag	10	8.55		10	
Matlang Bay	1 [9	10°53'08"N, 124°26'27"E/Matlang	<2.5				
Matlang Bay	1 [10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	<2.5				
Matlang Bay	1 1	11	10°52'13"N, 124°28'13"E/Tolingon	<2.5				
Dupon Bay		1	10°54'35"N, 124°26'05"E/Kinatumyan	< 0.02				
Dupon Bay	1 1	2	10°54'56"N, 124°24'0"E/Sacay Point	< 0.02				
Dupon Bay	1 1	3	10°54'50"N, 124°23'5"E/Buenavista	<0.02	<0.02	<0.02	<0.02	
Dupon Bay	1 1	4	10°53'34.4"N, 124°25'43.7"E/Libertad	< 0.02				
Camotes Sea	1 1	5	10°53'11"N, 124°26'04"E/Libertad	< 0.02	<0.02	<0.02	<0.02	
Matlang Bay	Cu (mg/L)	6	10"53'13.7"N, 124"26'30.1"E/Libertad	< 0.02	<0.02		-	0.02
Matlang Bay	NY LES PEA	7	10"53'18"N, 124°26'46"E,Brgy. Libertad	<0.02		<0.02	1	
Matlang Bay	1 I	8	10°53'42"N, 124°26'58"E/Sitio Pingag	< 0.02			<0.02	
Matlang Bay	1 [9	10°53'08"N, 124°26'27"E/Matlang	<0.02				
Matlang Bay	1 i	10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	< 0.02				
Matlang Bay	1 1	11	10°52'13"N, 124°28'13"E/Tolingon	<0.02				
Dupon Bay		1	10°54'35"N, 124°26'05"E/Kinatumyan	< 0.013	<0.013	<0.013		
Dupon Bay	1 1	2	10°54'56"N, 124°24'0"E/Sacay Point	<0.013				
Dupon Bay	1 1	3	10°54'50"N, 124°23'5"E/Buenavista	<0.013			<0.013	
Dupon Bay	1 1	4	10°53'34.4"N, 124°25'43.7"E/Libertad	< 0.013				
Camotes Sea	1 [5	10"53'11"N, 124°26'04"E/Libertad	<0.013	< 0.013	<0.013	<0.013	
Matlang Bay	As (mg/L)	6	10°53'13.7"N, 124°26'30.1"E/Libertad	< 0.013	<0.013			0.02
Matlang Bay	1 [7	10"53'18"N, 124"26'46"E,Brgy. Libertad	<0.013				
Matlang Bay	1 [8	10°53'42"N, 124°26'58"E/Sitio Pingag	< 0.013		<0.013	<0.013	
Matlang Bay] [9	10"53'08"N, 124°26'27"E/Matlang	< 0.013				
Matlang Bay] [10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	< 0.013]		l	
Matlang Bay		-11	10°52'13"N, 124°28'13"E/Tolingon	< 0.013				
Dupon Bay	2	1	10°54'35"N, 124°26'05"E/Kinatumyan	< 0.002				
Dupon Bay] [2	10"54'56"N, 124"24'0"E/Sacay Point	< 0.002	<0.002	<0.002	002 <0.002	
Dupon Bay	1 1	3	10°54'50"N, 124°23'5"E/Buenavista	<0.002				
Dupon Bay	1 1	4	10°53'34.4"N, 124°25'43.7"E/Libertad	< 0.002				

Camotes Sea		5	10°53'11"N, 124°26'04"E/Libertad	0.002	<0.002	<0.002	<0.002	
Matlang Bay	(mg/L)	6	10°53'13.7"N, 124"26'30.1"E/Libertad	<0.002				0.005
Matlang Bay		7	10°53'18"N, 124°26'46"E,Brgy. Libertad	<0.002		<0.002	- 1	
Matlang Bay	1900000000	8	10°53'42"N, 124°26'58"E/Sitio Pingag	0.007	<0.002		<0.002	
Matlang Bay	1 1	9	10°53'08"N, 124°26'27"E/Matlang	<0.002			1	
Matlang Bay	1 1	10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	<0.002			- 1	
Matlang Bay		11	10"52'13"N, 124°28'13"E/Tolingon	< 0.002				
Dupon Bay		1	10°54'35"N, 124"26'05"E/Kinatumyan	< 0.0004			1	
Dupon Bay	1 i	2	10°54'56"N, 124°24'0"E/Sacay Point	< 0.0004			- 1	
Dupon Bay	1 1	3	10°54'50"N, 124°23'5"E/Buenavista	< 0.0004	<0.0004	<0.0004	< 0.0004	
Dupon Bay	1 1	4	10"53'34.4"N, 124"25'43.7"E/Libertad	< 0.0004	1		1	
Camotes Sea	1 i	5	10"53'11"N, 124"26'04"E/Libertad	< 0.0004	<0.0004	<0.0004	< 0.0004	
Matlang Bay	Hg (mg/L)	6	10°53'13.7"N, 124°26'30.1"E/Libertad	< 0.0004				0.002
Matlang Bay	1 1	7	10°53'18"N, 124°26'46"E,Brgy. Libertad	< 0.0004			l l	
Matlang Bay	1 1	8	10"53'42"N, 124°26'58"E/Sitio Pingag	< 0.0004	<0.0004	<0.0004	<0.0004	
Matlang Bay	1 [9	10*53'08"N, 124*26'27"E/Matlang	< 0.0004				
Matlang Bay	1 1	10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	< 0.0004			- 1	
Matlang Bay		11	10"52'13"N, 124°28'13"E/Tolingon	< 0.0004				
Dupon Bay		1	10°54'35"N, 124°26'05"E/Kinatumyan	< 0.026				
Dupon Bay	1 I	2	10°54'56"N, 124°24'0"E/Sacay Point	< 0.026				
Dupon Bay	1 1	3	10°54'50"N, 124°23'5"E/Buenavista	0.037	0.0335	<0.026	0.037	
Dupon Bay	1 [4	10°53'34.4"N, 124°25'43.7"E/Libertad	0.030				
Camotes Sea	Pb (mg/L)	5	10"53'11"N, 124°26'04"E/Libertad	< 0.026	<0.026	<0.026	<0.026	
Matlang Bay	1	6	10°53'13.7"N, 124°26'30.1"E/Libertad	< 0.026				0.05
Matlang Bay] [7	10°53'18"N, 124°26'46"E,Brgy. Libertad	0.061				
Matlang Bay	1 [8	10°53'42"N, 124°26'58"E/Sitio Pingag	< 0.026	0.0437	<0.026	0.061	
Matlang Bay] [9	10°53'08"N, 124°26'27"E/Matlang	< 0.026				
Matlang Bay] [10	10"52'55"N, 124°27'52"E/Brgy. Bilwang	0.026	1			
Matlang Bay] [11	10°52'13"N, 124°28'13"E/Tolingon	0.044				
Dupon Bay		1	10°54'35"N, 124°26'05"E/Kinatumyan	0.001				
Dupon Bay] [2	10°54'56"N, 124°24'0"E/Sacay Point	0.004	1		1	
Dupon Bay] [3	10°54'50"N, 124°23'5"E/Buenavista	0.003	0.002	0.001	0.004	
Dupon Bay		4	10"53'34.4"N, 124°25'43.7"E/Libertad	0.001				

	Camotes Sea	Cr ⁺⁶ (mg/L)	5	10°53'11"N, 124°26'04"E/Libertad	0.006	0.006	0.006	0.006	0.05
	Matlang Bay		6	10"53'13.7"N, 124"26'30.1"E/Libertad	0.001				
	Matlang Bay		7	10"53'18"N, 124"26'46"E,Brgy. Libertad	0.006				
	Matlang Bay		8	10°53'42"N, 124°26'58"E/Sitio Pingag	0.003	0.0032	<0.001	0.006	
	Matlang Bay		9	10°53'08"N, 124°26'27"E/Matlang	0.004				1
	Matlang Bay		10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	< 0.001				
	Matlang Bay		11	10"52'13"N, 124°28'13"E/Tolingon	0.002	İ			
	Dupon Bay		1	10°54'35"N, 124°26'05"E/Kinatumyan	7				
	Dupon Bay	1	2	10°54'56"N, 124°24'0"E/Sacay Point	95		1 1		
	Dupon Bay	== :-	3	10°54'50"N, 124°23'5"E/Buenavista	-				
	Dupon Bay		4	10°53'34.4"N, 124°25'43.7"E/Libertad	1.4	1.4	1.4	1.4	
	Camotes Sea	1	5	10°53'11"N, 124°26'04"E/Libertad	<1.0	<1.0	<1.0	<1.0	3
	Matlang Bay	Oil & Grease	6	10°53'13.7"N, 124°26'30.1"E/Libertad	1.5	1.5	1.5	1.5	1
	Matlang Bay	(mg/L)	7	10°53'18"N, 124°26'46"E,Brgy. Libertad	2				
	Matlang Bay	I TOWN THE PARTY OF THE PARTY O	8	-					
	Matlang Bay		9	10°53'08"N, 124°26'27"E/Matlang					
	Matlang Bay	1	10	10°52'55"N, 124°27'52"E/Brgy. Bilwang	1,000	1	1 1		
	mounty out		10	10 32 33 N, 124 27 32 C/Digy. Dilwang			1 1		
	Matlang Bay		11	10°52'13"N, 124°28'13"E/Tolingon	2				
egion		Parameter		- 1		Average	Min	Max	Criterion
egion		Parameter	- 11	10°52'13"N, 124°28'13"E/Tolingon Stn. ID Ormoc Bay, Ormoc City (Class SC)	2	Average	Min	Max	Criterion
egion		Parameter	- 11	10°52'13"N, 124°28'13"E/Tolingon Stn. ID	2	Average	Min	Max	Criterion
vill		Parameter	- 11	10°52'13"N, 124°28'13"E/Tolingon Stn. ID Ormoc Bay, Ormoc City (Class SC)	2	Average	Min	Max	Criterion
		Parameter	Stn. No.	10°52'13"N, 124°28'13"E/Tolingon Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022	(5 Stations)	Average	Min	Max	Criterion
		Parameter DO, mg/L	Stn. No.	10°52'13"N, 124°28'13"E/Tolingon Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant	(5 Stations)	Average 6.00	Min 5.8	Max 6.2	
	Mattang Bay		11 Stn. No.	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall	6.2 6.1 6 5.9				
	Mattang Bay		11 Stn. No.	10°52'13"N, 124°28'13"E/Tolingon Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall	6.2 6.1 6				Criterion 5 mg/L (minimum
	Mattang Bay		11 Stn. No.	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall	6.2 6.1 6 5.9				
	Mattang Bay		11 Stn. No.	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting OSCO Canal	6.2 6.1 6 5.9 5.8				5 mg/L (minimum
	Mattang Bay		11 Stn. No. 1 2 3 4 5 1	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting OSCO Canal Fronting Crushing Plant	6.2 6.1 6 5.9 5.8 64				
	Mattang Bay Ormoc Bay	DO, mg/L	11 Stn. No. 1 2 3 4 5 1 2	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting OSCO Canal Fronting Crushing Plant Left of LAC Outfall	6.2 6.1 6 5.9 5.8 64 63	6.00	5.8	6.2	5 mg/L (minimum
	Mattang Bay Ormoc Bay	DO, mg/L	11 Stn. No. 1 2 3 4 5 1 2 3 3	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting OSCO Canal Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Fronting Crushing Plant Left of LAC Outfall Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall	6.2 6.1 6 5.9 5.8 64 63 41	6.00	5.8	6.2	5 mg/L (minimum
	Mattang Bay Ormoc Bay	DO, mg/L	11 Stn. No.	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting Crushing Plant Left of LAC Outfall Right of LAC Outfall Fronting Crushing Plant Left of LAC Outfall Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Fronting LAC Outfall Right of LAC Outfall	6.2 6.1 6 5.9 5.8 64 63 41 37	6.00	5.8	6.2	5 mg/L (minimum
	Mattang Bay Ormoc Bay	DO, mg/L TSS mg/L	11 Stn. No. 1 2 3 4 5 1 2 3 4 5	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting OSCO Canal Fronting Crushing Plant Left of LAC Outfall Fronting Crushing Plant Left of LAC Outfall Fronting Crushing Plant Left of LAC Outfall Fronting Crushing Plant Fronting LAC Outfall Fronting LAC Outfall Right of LAC Outfall Fronting OSCO Canal	6.2 6.1 6 5.9 5.8 64 63 41 37 21	6.00	5.8	6.2	5 mg/L (minimum
	Mattang Bay Ormoc Bay	DO, mg/L	11 Stn. No.	Stn. ID Ormoc Bay, Ormoc City (Class SC) 05/02/2022 Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Fronting OSCO Canal Fronting Crushing Plant Left of LAC Outfall Fronting Crushing Plant Fronting Crushing Plant Fronting Crushing Plant Left of LAC Outfall Fronting LAC Outfall Fronting LAC Outfall Fronting Crushing Plant Fronting Crushing Plant Fronting OSCO Canal Fronting OSCO Canal Fronting Crushing Plant	6.2 6.1 6 5.9 5.8 64 63 41 37 21 8.18	6.00	5.8	6.2	5 mg/L (minimum

		5	Fronting OSCO Canal	8.21				
		1	Fronting Crushing Plant	27.2				
	Temp. [©] C	2	Left of LAC Outfall	27.2		27.1	27.2	25-31
Ormoc Bay		3	Fronting LAC Outfall	27.1	27,16			
		4	Right of LAC Outfall	27.2				
l-		5	Fronting OSCO Canal	27.1				
T T		1	Fronting Crushing Plant	5				
	l f	2	Left of LAC Outfall	5		5	5	10
Ormoc Bay	Color	3	Fronting LAC Outfall	5	5			
	(TCU)	4	Right of LAC Outfall	5				
	N 10	5	Fronting OSCO Canal	5				
	Nitrates (mg/L)	1	Fronting Crushing Plant	3.55	6.13	ND	8.57	
		2	Left of LAC Outfall	ND				
Ormoc Bay		3	Fronting LAC Outfall	8.57				10
		4	Right of LAC Outfall	8.46				
	AUCEN :	5	Fronting OSCO Canal	3.94		ar.		
		1	Fronting Crushing Plant	0.016				
		2	Left of LAC Outfall	0.031	0.0226			0.05
Ormoc Bay	Phosphates	3	Fronting LAC Outfall	0.014		0.016	0.031	
	(mg/L)	4	Right of LAC Outfall	0.03				
	5 MANAGES	5	Fronting OSCO Canal	0.022				

Note: 1. All results for this quarter are all within the Water Quality Guidelines for Class SC Waters of DAO 2016-08

2 Based on the new Administrative Order (AO) 2021-19 published on June 30, 2021, "the Updated Water Quality Guidelines and General Effluent Standards for selected parameters", the scope for copper was changed from Dissolved Copper to Total Copper

Prepared by:

ROSARIO S. VIDTOHAN

EMS H

Reviewed by:

ARNEL L. IFE

OIC- Chief, Ambient Monitoring Section

Approved by:

OIC-Chief, Environmental Monitoring & Enforcement Division

Noted by:

ENGR. REYNALDO B. BARRA, PINE

OIC, Regional Director