Spanning Tree from PVST+ to Rapid-PVST Migration Configuration Example

Document ID: 72836

Contents
Introduction
Prerequisites
Requirements
Components Used
Conventions
Background Information
Configure
Network Diagram
Configurations
PVST+ Configuration
UplinkFast and BackboneFast
Rapid-PVST+ Migration
Debug Output - Mixed Mode
Debug Output - Rapid-PVST+ Mode
Verify
Troubleshoot
Cisco Support Community - Featured Conversations

Introduction

Related Information

This document provides a sample configuration to migrate the spanning tree mode from PVST+ to rapid-PVST+ in the campus network. It also explains the PVST+ configuration, Spanning Tree load balancing, and the UplinkFast and BackboneFast features.

Prerequisites

Requirements

It is recommended to read <u>Understanding Rapid Spanning Tree Protocol (802.1w)</u> before you configure rapid-PVST+.

This table shows the support of Rapid Spanning Tree Protocol (RSTP) in Catalyst switches, and the minimum software required for that support.

Catalyst Platform	Rapid-PVST+
Catalyst 2900 XL / 3500 XL	Not available.
Catalyst 2940	12.1(20)EA2
Catalyst 2950/2955/3550	12.1(13)EA1
Catalyst 2970/3750	12.1(14)EA1
Catalyst 3560	12.1(19)EA1
Catalyst 3750 Metro	12.1(14)AX
Catalyst 2948G-L3/4908G-L3	Not available.
Catalyst 4000/2948G/2980G (CatOS)	7.5
Catalyst 4000/4500 (IOS)	12.1(19)EW
Catalyst 5000/5500	Not available.
Catalyst 6000/6500	7.5
Catalyst 6000/6500 (IOS)	12.1(13)E
Catalyst 8500	Not available.

Components Used

The information in this document is based on Cisco IOS® Software Release12.2(25) and CatOS 8.5(8). However, the configuration is applicable on the minimum Cisco IOS version shown in the table.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

Conventions

Refer to Cisco Technical Tips Conventions for more information on document conventions.

Background Information

802.1D Spanning Tree Protocol (STP) has a drawback of slow convergence. Cisco Catalyst switches support three types of STPs, which are PVST+, rapid-PVST+ and MST. PVST+ is based on IEEE802.1D standard and includes Cisco proprietary extensions such as BackboneFast, UplinkFast, and PortFast. Rapid-PVST+ is based on IEEE 802.1w standard and has a faster convergence than 802.1D. RSTP (IEEE 802.1w) natively includes most of the Cisco proprietary enhancements to the 802.1D Spanning Tree, such as BackboneFast and UplinkFast. Rapid-PVST+ has these unique features:

 Uses Bridge Protocol Data Unit (BPDU) version 2 which is backward compatible with the 802.1D STP, which uses BPDU version 0.

- All the switches generate BPDUs and send out on all the ports every 2 seconds, whereas in 802.1D STP only the root bridge sends the configuration BPDUs.
- Port Roles—Root port, designated port, alternate port and backup port.
- Port States—Discarding, Learning, and Forwarding.
- Port Types—Edge Port (PortFast), Point-to-Point and Shared port.

Rapid-PVST uses RSTP to provide faster convergence. When any RSTP port receives legacy 802.1D BPDU, it falls back to legacy STP and the inherent fast convergence benefits of 802.1w are lost when it interacts with legacy bridges.

Configure

This example contains two sections. The first section shows the current PVST+ configuration. The second section shows the configuration to migrate from PVST+ to rapid-PVST+.

Note: Use the Command Lookup Tool (registered customers only) to obtain more information on the commands used in this section


Network Diagram

This document uses this network setup:

This diagram has these switches:

- Distribution1 and Distribution2, which are in the distribution layer
- Two access-layer switches called Access1 (IOS) and Access2 (CatOS)
- Two server aggregation switches called Services1 and Services2

VLANs 10, 30, and 100 carry data traffic. VLANs 20, 40, and 200 carry voice traffic.



Configurations

This document uses these configurations:

- PVST+ Configuration
- Rapid-PVST+ Migration

PVST+ Configuration

The switches are configured in PVST+ to carry the data and voice traffic as per the network diagram. This is a short summary of the configuration:

The Distribution1 switch is configured to become a primary root bridge for the data VLANs 10, 30, 100 using the
 Distribution1(config)# spanning-tree vlan 10,30,100 root primary command, and the secondary root bridge for the
 voice VLANs 20, 40, 200 uses the Distribution1(config)# spanning-tree vlan 20,40,200 root secondary command.

Note: The spanning-tree root primary command alters the switch's bridge priority to 8192 and the spanning-tree root secondary command alters the priority to 16384.

• The Distribution2 switch is configured to become a primary root bridge for the voice VLANs 20, 40, 200 using the

Distribution2(config)# spanning-tree vlan 20,40,200 root primary command, and the secondary root bridge for the data VLANs 10, 30, 100 uses the Distribution2(config)# spanning-tree vlan 10,30,100 root secondary command.

- The spanning-tree backbonefast command is configured on all the switches to converge the STP faster in case of indirect link failure in the network.
- The spanning-tree uplinkfast command is configured on the access-layer switches to converge the STP faster in
 case of direct uplink failure.

```
Distribution1
Distribution1#show running-config
Building configuration...
spanning-tree mode pvst
spanning-tree extend system-id
spanning-tree backbonefast
spanning-tree vlan 10,30,100 priority 8192
spanning-tree vlan 20,40,200 priority 16384
vlan 10,20,30,40,100,200
interface FastEthernet1/0/1
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 10,20
interface FastEthernet1/0/3
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 30,40
interface FastEthernet1/0/5
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 100,200
interface FastEthernet1/0/23
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 10,20,30,40,100,200
interface FastEthernet1/0/24
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 10,20,30,40,100,200
end
```

You can see that the port Fa1/0/24 is configured with the **spanning-tree vlan 20,40,200 port-priority 64** command. Distribution2 is configured root for VLANs 20,40,200. Distribution2 has two links to Distribution1: Fa1/0/23 and Fa1/0/24. Both ports are designated ports for VLANs 20, 40, 200 because Distribution2 is the root for those VLANs. Both ports have the same priority 128 (default). Also, these two links have the same cost from Distribution1: fa1/0/23 and fa1/0/24. Distribution1 chooses the lowest port number of the two ports in order to set the port into the Forwarding state. The lowest port number is Fa1/0/23. However, as per the network diagram, voice VLANs 20, 40, 200 should flow through Fa1/0/24. You can accomplish this with these methods:

- 1. Decrease the port cost in Distribution1: Fa1/0/24
- 2. Decrease the port priority in Distribution2: Fa1/0/24

In this example, port priority is decreased to forward VLANs 20, 40, 200 through fa1/0/24.

```
Distribution2

Distribution2#show running-config

Building configuration...
!

spanning-tree mode pvst
spanning-tree extend system-id
spanning-tree backbonefast
spanning-tree vlan 10,30,100 priority 28672
spanning-tree vlan 20,40,200 priority 24576
!

vlan 10,20,30,40,100,200
!
interface FastEthernet1/0/2
switchport trunk encapsulation dotlq
switchport mode trunk
```

```
switchport trunk allowed vlan 10,20
interface FastEthernet1/0/4
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 30,40
interface FastEthernet1/0/6
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 100,200
interface FastEthernet1/0/23
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 10,20,30,40,100,200
interface FastEthernet1/0/24
switchport trunk encapsulation dot1q
switchport mode trunk
spanning-tree vlan 20,40,200 port-priority 64
switchport trunk allowed vlan 10,20,30,40,100,200
```

You can see that port Fa0/5 in Services1, and both Fa0/6 and Fa0/48 in Services2 have Spanning Tree port cost and port priority configuration. Here the STP is tuned so that VLAN 100 and 200 of Services1 and Services2 can pass through the trunk links between them. If this configuration is not applied, Services1 and 2 will not pass traffic through the trunk links between them. Instead, it chooses the path through Distribution1 and Distribution2.

Services2 sees two equal cost paths to the VLAN 100 root (Distribution1). One via Services1, the second one via Distribution2. The STP chooses the best path (root port) in this order:

- Path cost
- 2. The bridge ID of the forwarding switch
- 3. Lowest port priority
- 4. Lowest internal port number

In this example, both the paths have the same cost. However, the Distribution2 (24576) has lower priority than Services1 (32768) for the VLAN 100. Therefore, Services2 chooses Distribution2. In this example, port cost on Services1: fa0/5 is set lower to let Services2 choose the Services1. The path cost overrides the forwarding switch priority number.

```
Services1
Services1#show running-config
Building configuration...
spanning-tree mode pvst
spanning-tree portfast bpduguard default
spanning-tree extend system-id
spanning-tree backbonefast
vlan 100,200
interface FastEthernet0/5
switchport trunk encapsulation dot1q
switchport mode trunk
spanning-tree vlan 100 cost 18
switchport trunk allowed vlan 100,200
interface FastEthernet0/47
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 100,200
interface FastEthernet0/48
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 100,200
```

The same concept is applied for Services1 to choose Services2 to forward VLAN 200. After you reduce the cost for VLAN 200 in Services2 - fa0/6, Services1 chooses fa0/47 to forward VLAN 200. However, the requirement here is to forward VLAN 200 through fa0/48. You can accomplish with these two methods:

- 1. Decrease the port cost in Services1: Fa0/48
- 2. Decrease the port priority in Services2: Fa0/48

In this example, port priority in Services2 is decreased to forward VLAN 200 through fa0/48.

```
Services2
Services2#show running-config
Building configuration...
spanning-tree mode pvst
spanning-tree portfast bpduguard default
spanning-tree extend system-id
spanning-tree backbonefast
vlan 100,200
interface FastEthernet0/6
switchport trunk encapsulation dot1q
switchport mode trunk
spanning-tree vlan 200 cost 18
switchport trunk allowed vlan 100,200
interface FastEthernet0/47
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 100,200
interface FastEthernet0/48
switchport trunk encapsulation dot1q
switchport mode trunk
spanning-tree vlan 200 port-priority 64
switchport trunk allowed vlan 100,200
end
```

```
Access1
Access1#show running-config
Building configuration...
spanning-tree mode pvst
spanning-tree portfast bpduguard default
spanning-tree extend system-id
spanning-tree uplinkfast
spanning-tree backbonefast
vlan 10,20
interface FastEthernet0/1
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 10,20
interface FastEthernet0/2
switchport trunk encapsulation dot1q
switchport mode trunk
switchport trunk allowed vlan 10,20
end
```

```
Access2
Access2> (enable)show config all

#mac address reduction
set spantree macreduction enable
!
#stp mode
set spantree mode pvst+
!
#uplinkfast groups
set spantree uplinkfast enable rate 15 all-protocols off
!
#backbonefast
set spantree backbonefast enable
```

```
#vlan parameters
set spantree priority 49152 1
set spantree priority 49152 30
set spantree priority 49152 40
!
#vlan(defaults)
set spantree enable 1,30,40
set spantree fwddelay 15 1,30,40
set spantree hello 2 1,30,40
set spantree maxage 20 1,30,40
!
#vtp
set vlan 1,30,40
!
#module 3 : 48-port 10/100BaseTX Ethernet
set trunk 3/3 on dotlq 30,40
set trunk 3/4 on dotlq 30,40
!
end
```

UplinkFast and BackboneFast

It is good to know the UplinkFast and BackboneFast behavior before you start the migration process. In the network diagram, the Access1 switch runs Cisco IOS. This output is taken before migration to the rapid-PVST+ mode:

Access1#show spanning-tree vlan 10

```
VLAN0010
  Spanning tree enabled protocol ieee
  Root ID
            Priority 24586
            Address
                        0015.63f6.b700
            Cost 3019
Port 107 (FastEthernet3/0/1)

May Age 20 sec
            Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec
  Bridge ID Priority
                        49162 (priority 49152 sys-id-ext 10)
            Address 000f.f794.3d00
Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec
            Aging Time 300
 Uplinkfast enabled
Interface
               Role Sts Cost
                                 Prio.Nbr Type
------
Fa3/0/1 Root FWD 3019 128.107 P2p
Fa3/0/2 Altn BLK 3019 128.108 P2p
```

Access1#show spanning-tree summary

Switch is in pvst mode
Root bridge for: none
Extended system ID is enabled
Portfast Default is disabled
Portfast BPDU Guard Default is enabled
Portfast BPDU Filter Default is disabled
Loopguard Default is disabled
Loopguard Default is disabled
UplinkFast is enabled
BackboneFast is enabled
Configured Pathcost method used is short

Name	Blocking	Listening	Learning	Forwarding	STP Active
VLAN0010	1	0	0	1	2
VLAN0020	1	0	0	1	2
2 vlans	2	0	0	2	4

This output is taken after the mode is changed to rapid-PVST+:

Access1#show spanning-tree vlan 10

```
VLAN0010
Spanning tree enabled protocol rstp
Root ID Priority 24586
```

Address 0015.63f6.b700

Cost **3019**

Port 107 (FastEthernet3/0/1)

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Bridge ID Priority 49162 (priority 49152 sys-id-ext 10)

Address 000f.f794.3d00

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Aging Time 300

UplinkFast enabled but inactive in rapid-pvst mode

Interface	Role	Sts	Cost	Prio.Nbr	Type
Fa3/0/1	Root	FWD	3019	128.107	P2p
Fa3/0/2	Altn	BLK	3019	128.108	P2p

Access1#show spanning-tree summary

Switch is in rapid-pvst mode

Root bridge for: none

Extended system ID is enabled Portfast Default is disabled PortFast BPDU Guard Default is enabled Portfast BPDU Filter Default is disabled Loopguard Default is disabled EtherChannel misconfig guard is enabled

UplinkFast is enabled but inactive in rapid-pvst mode BackboneFast is enabled but inactive in rapid-pvst mode

Configured Pathcost method used is short

Name	Blocking	Listening	Learning	Forwarding	STP Active
VLAN0010	1	0	0	1	2
VLAN0020	1	0	0	1	2
2 vlans	2	0	0	2	4

You can see in the **show spanning-tree summary** command output that UplinkFast and BackboneFast are enabled, but are inactive in rapid-PVST mode. It is optional to remove both the commands. It does not affect any of the rapid-PVST operation if you do not remove the commands. If you disable the UplinkFast with the **no spanning-tree uplinkfast** configuration mode command, the bridge priority and port cost revert back to default. It is advisable to have the bridge priority of the non-root switch as a higher number. This output shows after the UplinkFast feature is disabled in the rapid-PVST mode:

Access1#show spanning-tree vlan 10

VLAN0010

Spanning tree enabled protocol rstp

Root ID Priority 24586

Address 0015.63f6.b700

Cost 19

Port 107 (FastEthernet3/0/1)

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Bridge ID Priority 32778 (priority 32768 sys-id-ext 10)

Address 000f.f794.3d00

Hello Time $\,$ 2 sec $\,$ Max Age 20 sec $\,$ Forward Delay 15 sec

Aging Time 300

In	terface	Role	Sts	Cost	Prio.Nbr	Туре
Fa	3/0/1	Root	FWD	19	128.107	P2p
Fa	3/0/2	Altn	BLK	19	128.108	P2p

Access1#show spanning-tree summary

Switch is in rapid-pvst mode

Root bridge for: none

Extended system ID is enabled Portfast Default is disabled PortFast BPDU Guard Default is enabled Portfast BPDU Filter Default is disabled Loopguard Default is disabled therChannel misconfig guard is enabled UplinkFast is disabled

BackboneFast is enabled but inactive in rapid-pvst mode

Configured Pathcost method used is short

VLAN0010	1	0	0	1	2
VLAN0020	1	0	0	1	2
2 vlans	2	0	0	2	4

CatOS does not allow you to change the mode to rapid-PVST if the BackboneFast feature is enabled. You have to disable BackboneFast before the migration. UplinkFast acts as same as it behaves in IOS.

Access2> (enable) set spantree mode rapid-pvst+ Cannot change the spantree mode to RAPID-PVST+ when backbonefast is enabled.

Rapid-PVST+ Migration

Rapid-PVST+ uses the same BPDU format as the 802.1D and it is backward compatible. It is difficult to convert all the switches in the enterprise network at the same time to rapid-PVST+. Because of the backward compatibility, you can convert phase by phase. It is recommended to implement the changes in the scheduled maintenance window because the spanning tree reconfiguration disrupts the traffic flow. Spanning Tree UplinkFast and BackboneFast features are PVST+ features. These are disabled when you enable rapid-PVST+ because those features are built within rapid-PVST+. Therefore, during the migration you can remove those commands. The configuration of the features such as PortFast, BPDUguard, BPDUfilter, root guard, and loopguard are applicable in rapid-PVST+ mode also. The usage of these features are the same as in PVST+ mode. If you have already enabled these features in the PVST+ mode, the features remain active after the migration to rapid-PVST+ mode. In this example, migration occurs in this order:

- 1. Access1
- 2. Access2
- 3. Services1 and Services2
- 4. Distribution1 and Distribution2
- 1. Access1 migration:

```
Access1(config)#spanning-tree mode rapid-pvst
Access1(config)#no spanning-tree uplinkfast
Access1(config)#no spanning-tree backbonefast
```

Access1#show spanning-tree vlan 10

VLAN0010

Spanning tree enabled protocol rstp

Address 000f.f794.3d00
Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec
Aging Time 300

Interface	Role S	Sts	Cost	Prio.Nbr	Туре
Fa3/0/1	Root F	WD	19	128.107	P2p Peer(STP)
Fa3/0/2	Altn E	ЗLК	19	128.108	P2p Peer(STP)

!--- Type P2p Peer(STP) represents that the neighbor switch runs PVST.

2. Access2 migration:

Access2> (enable) set spantree backbonefast disable Backbonefast disabled for all VLANs.

```
Access2> (enable) set spantree mode rapid-pvst+
PVST+ database cleaned up.
Spantree mode set to RAPID-PVST+.
```

```
Access2> (enable) clear spantree uplinkfast
This command will cause all portcosts port
```

This command will cause all portcosts, portvlancosts, and the bridge priority on all vlans to be set to default. Do you want to continue (y/n) [n]? y VLANs 1-4094 bridge priority set to 32768.

```
The port cost of all bridge ports set to default value. The portvlancost of all bridge ports set to default value. uplinkfast all-protocols field set to off. uplinkfast disabled for bridge.
```

3. Services1 and Services2 migration:

```
Services1(config)#spanning-tree mode rapid-pvst
Services1(config)#no spanning-tree backbonefast
Services2(config)#spanning-tree mode rapid-pvst
Services2(config)#no spanning-tree backbonefast
```

4. Distribution1 and Distribution2 migration:

```
Distribution1(config)#spanning-tree mode rapid-pvst
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan10, changed state to
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan20, changed state to
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan30, changed state to
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan40, changed state to
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan100, changed state to
up
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan200, changed state to
up
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan40, changed state to
down
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan30, changed state to
down
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan40, changed state to
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan30, changed state to
!--- Distribution1 switch has Layer3 VLAN interfaces and it goes
!--- down and up during the conversion.
```

Distribution1(config)#no spanning-tree backbonefast

Distribution2(config)#spanning-tree mode rapid-pvst

```
2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan1, changed state to own 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan1, changed state to p 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan10, changed state to up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan20, changed state to up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan30, changed state to up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan40, changed state to up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan40, changed state to up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan200, changed state t up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan200, changed state t up 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan30, changed state to down 2d02h: %LINEPROTO-5-UPDOWN: Line protocol on Interface Vlan30, changed state to up
```

!--- Distribution2 switch has Layer3 VLAN interfaces and it goes !--- down and up during the conversion.

Distribution2(config)#no spanning-tree backbonefast

Debug Output - Mixed Mode

receive the complete advantages of rapid-PVST+. The overall convergence time is the same as the convergence time of PVST+ mode. In order to take full advantage of rapid-PVST+, all the switches in the spanning tree topology must run the rapid-PVST+. In order to show how the spanning tree behaves in the mixed mode, a sample **debug** command output is shown here. Distribution1 and Distribution2 are in PVST+, and Access1 is in rapid-PVST+ mode.

The debug spanning-tree command output shows the STP operation when the link between Access1 and Distribution1 fails.

Access1

```
00:55:13: RSTP(10): updt roles, root port Fa0/1 going down
00:55:13: RSTP(10): Fa0/2 is now root port
00:55:13: RSTP(10): Fa0/2 received a tc ack
00:55:15: %LINK-5-CHANGED: Interface FastEthernet0/1, changed state to adminis tratively down
00:55:16: %LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet0/1, changed state to down
```

Distribution1

```
00:55:20: STP: VLAN0010 Topology Change rcvd on Fal/0/23
00:55:20: STP: VLAN0020 sent Topology Change Notice on Fal/0/24
00:55:21: %LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet1/0/1, changed state to down
00:55:22: %LINK-3-UPDOWN: Interface FastEthernet1/0/1, changed state to down
```

Distribution2

```
00:55:06: STP: VLAN0010 Topology Change rcvd on Fal/0/2 00:55:06: STP: VLAN0010 sent Topology Change Notice on Fal/0/23
```

The **debug spanning-tree** command output shows the STP operation when the link between Access1 and Distribution1 is up.

Access1

```
00:55:40: %LINK-3-UPDOWN: Interface FastEthernet0/1, changed state to up
00:55:43: STP: PVST vlan 10 port Fa0/1 created, ext id 2E42430, vp 3389640
00:55:43: RSTP(10): initializing port Fa0/1
00:55:43: RSTP(10): Fa3/0/1 is now designated
00:55:43: STP: PVST vlan 20 port Fa0/1 created, ext id 2E42430, vp 300EC20
00:55:43: RSTP(20): initializing port Fa0/1
00:55:43: RSTP(20): Fa0/1 is now designated
00:55:43: RSTP(10): transmitting a proposal on Fa0/1
00:55:43: RSTP(20): transmitting a proposal on Fa0/1
00:55:43: RSTP(10): transmitting a proposal on Fa0/1
00:55:43: RSTP(20): transmitting a proposal on Fa0/1
00:55:43: RSTP(10): updt roles, received superior bpdu on Fa0/1
00:55:43: RSTP(10): Fa0/1 is now root port
00:55:43: RSTP(10): Fa0/2 blocked by re-root
00:55:43: RSTP(10): Fa0/2 is now alternate
00:55:44: %LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet0/1, cha
nged state to up
00:55:44: RSTP(20): updt roles, received superior bpdu on Fa0/1
00:55:44: RSTP(20): Fa0/1 is now alternate
```

Distribution1

```
00:55:49: %LINK-3-UPDOWN: Interface FastEthernet1/0/1, changed state to up 00:55:50: set portid: VLAN0010 Fa1/0/1: new port id 8001 00:55:50: STP: PVST vlan 10 port Fa1/0/1 created, ext id 2DA13A8, vp 3BDB708 00:55:50: STP: VLAN0010 Fa1/0/1 -> listening 00:55:50: set portid: VLAN0020 Fa1/0/1: new port id 8001 00:55:50: STP: PVST vlan 20 port Fa1/0/1 created, ext id 2DA13A8, vp 3C06F20 00:55:50: STP: VLAN0020 Fa1/0/1 -> listening 00:55:51: %LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet1/0/1, changed state to up 00:56:05: STP: VLAN0010 Fa1/0/1 -> learning 00:56:05: STP: VLAN0020 Fa1/0/1 -> learning 00:56:20: STP: VLAN0020 Fa1/0/1 -> forwarding 00:56:20: STP: VLAN0020 sent Topology Change Notice on Fa1/0/24 00:56:20: STP: VLAN0020 Fa1/0/1 -> forwarding
```

```
!--- This output is evident that the Access1 switch waits for the !--- standard 802.1D Spanning Tree process of listening, learning and forwarding !--- to complete in Distribution1.
```

Distribution2

```
00:55:06: STP: VLAN0020 Topology Change rcvd on Fal/0/24 00:56:06: STP: VLAN0020 Topology Change rcvd on Fal/0/24 !--- This output shows that Distribution2 is notified !--- about the indirect link outage by TCN BPDUs.
```

Debug Output - Rapid-PVST+ Mode

The Distribution1, Distribution2 and Access1 switches are in rapid-PVST+ mode. The **debug spanning-tree** command output shows the STP operation when the link between Access1 and Distribution1 fails.

Access1

```
01:31:04: RSTP(10): updt roles, root port Fa0/1 going down 01:31:04: RSTP(10): Fa0/2 is now root port 01:31:06: %LINK-5-CHANGED: Interface FastEthernet0/1, changed state to adminis tratively down 01:31:07: %LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet0/1, changed state to down
```

Distribution1

```
01:31:13: %LINEPROTO-5-UPDOWN: Line protocol on Interface FastEthernet1/0/1, changed state to down 01:31:14: %LINK-3-UPDOWN: Interface FastEthernet1/0/1, changed state to down
```

The **debug spanning-tree** command output shows the STP operation when the link between Access1 and Distribution1 is

Access1

```
01:35:46: %LINK-3-UPDOWN: Interface FastEthernet0/1, changed state to up
01:35:48: STP: PVST vlan 10 port Fa3/0/1 created, ext id 2E42430, vp 3C8E360
01:35:48: RSTP(10): initializing port Fa3/0/1
01:35:48: RSTP(10): Fa3/0/1 is now designated
01:35:48: STP: PVST vlan 20 port Fa3/0/1 created, ext id 2E42430, vp 3C8E3E0
01:35:48: RSTP(20): initializing port Fa3/0/1
01:35:48: RSTP(20): Fa3/0/1 is now designated
01:35:48: RSTP(10): updt roles, received superior bpdu on Fa3/0/1
01:35:48: RSTP(10): Fa3/0/1 is now root port
01:35:48: RSTP(10): Fa3/0/2 blocked by re-root
01:35:48: RSTP(10): synced Fa3/0/1
01:35:48: RSTP(10): Fa3/0/2 is now alternate
01:35:48: RSTP(20): updt roles, received superior bpdu on Fa3/0/1
01:35:48: RSTP(20): Fa3/0/1 is now alternate
01:35:48: RSTP(10): transmitting an agreement on Fa3/0/1 as a response to a prop
osal
```

Distribution1

```
01:35:55: %LINK-3-UPDOWN: Interface FastEthernet1/0/1, changed state to up
01:35:56: STP: PVST vlan 10 port Fa1/0/1 created, ext id 2DA13A8, vp 3BDCCD8
01:35:56: RSTP(10): initializing port Fa1/0/1
01:35:56: RSTP(10): Fa1/0/1 is now designated
01:35:56: STP: PVST vlan 20 port Fal/0/1 created, ext id 2DA13A8, vp 2D21C60
01:35:56: RSTP(20): initializing port Fa1/0/1
01:35:56: RSTP(20): Fa1/0/1 is now designated
01:35:56: RSTP(10): transmitting a proposal on Fa1/0/1
01:35:56: RSTP(20): transmitting a proposal on Fal/0/1
01:35:56: RSTP(10): received an agreement on Fa1/0/1
01:35:57: RSTP(20): transmitting a proposal on Fa1/0/1
01:35:59: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:01: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:03: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:06: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:08: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:10: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:11: RSTP(20): Fa1/0/1 fdwhile Expired
01:36:12: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:14: RSTP(20): transmitting a proposal on Fa1/0/1
```

```
01:36:16: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:18: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:20: RSTP(20): transmitting a proposal on Fal/0/1
01:36:22: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:24: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:26: RSTP(20): transmitting a proposal on Fa1/0/1
01:36:26: RSTP(20): Fa1/0/1 fdwhile Expired
!--- Distribution1 puts the port Fa1/0/1 as designated for VLANs 10 and 20.
!--- It also proposes that Fal/0/1 is designated for VLANs 10, 20. Access1 agrees with the
!--- proposal for VLAN10. However, it does not agree with the proposal for VLAN20 because it
!--- has the superior BPDU for VLAN20 from Distribution2.
```

Verify

Use this section to confirm that your configuration works properly.

 $\label{thm:continuous} The \ \underline{Output \ Interpreter \ Tool} \ (\underline{registered} \ customers \ only) \ (OIT) \ supports \ certain \ \underline{show} \ commands. \ Use \ the \ OIT \ to \ view \ an \ \underline{show} \ commands.$ analysis of **show** command output.

It is recommended to verify the spanning tree topology every time the configuration is changed.

Verify that the Distribution1 switch is the root bridge for data VLANs 10, 30, 100. Also, verify that the spanning tree forwarding path matches as per the path in the <u>network diagram</u>.

Distribution1#show spanning-tree vlan 10

```
VLAN0010
```

Fa1/0/24

Spanning tree enabled protocol rstp Root ID Priority 24586 0015.63f6.b700 Address This bridge is the root Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec Bridge ID Priority Address 24586 (priority 24576 sys-id-ext 10) 0015.63f6.b700 Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec Aging Time 300 Interface Role Sts Cost Prio.Nbr Type ----- ---- ----Fa1/0/1 Desg FWD 19 128.1 Desg FWD 19 128.3 P2p Fa1/0/3 128.5 P2p 128.23 P2p Desg FWD 19 Desg FWD 19 Fa1/0/5 Fa1/0/23

128.24 P2p

Access1#show spanning-tree summary Switch is in rapid-pvst mode

Root bridge for: none Extended system ID is enabled Portfast Default is disabled PortFast BPDU Guard Default is enabled Portfast BPDU Filter Default is disabled Loopguard Default is disabled EtherChannel misconfig guard is enabled is disabled UplinkFast BackboneFast is disabled Configured Pathcost method used is short

Desg FWD 19

Name	Blocking	Listening	Learning	Forwarding	STP Active	
VLAN0010	1	0	0	1	2	
VLAN0020	1	0	0	1	2	
2 vlans	2	0	0	2	4	

Access2> (enable) show spantree 30

VLAN 30

Spanning tree mode RAPID-PVST+ Spanning tree type ieee

Spanning tree enabled

Designated Root 00-15-63-f6-b7-00
Designated Root Priority 24606
Designated Root Cost 19
Designated Root Port 3/3

Root Max Age 20 sec Hello Time 2 sec Forward Delay 15 sec

Bridge ID MAC ADDR 00-d0-00-50-30-1d Bridge ID Priority 32768

Bridge Max Age 20 sec Hello Time 2 sec Forward Delay 15 sec

Role Cost Port State Prio Type ___________ forwarding ROOT 19 32 P2P blocking ALTR 19 32 P2P 3/3 3/4

Access2> (enable) show spantree 40

VLAN 40

RAPID-PVST+ Spanning tree mode

Spanning tree type ieee

Spanning tree enabled

Designated Root 00-15-c6-c1-30-00

Designated Root Priority 24616 Designated Root Cost 19
Designated Root Port 3/4 3/4

20 sec Hello Time 2 sec Forward Delay 15 sec Root Max Age

Bridge ID MAC ADDR 00-d0-00-50-30-27 Bridge ID Priority 32768

Bridge Max Age 20 sec Hello Time 2 sec Forward Delay 15 sec

Prio Type State Role Cost _____________ blocking ALTR 19 32 P2P forwarding ROOT 19 32 P2P 3/3 3/4

Services1#show spanning-tree vlan 100

VLAN0100

Spanning tree enabled protocol rstp

Root ID Priority 24676

Address 0015.63f6.b700
Cost 18
Port 7 (FastEthernet0/5)

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Bridge ID Priority 32868 (priority 32768 sys-id-ext 100)
Address 0003.fd63.bb80
Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Aging Time 300

Interface Role Sts Cost Prio.Nbr Type _____________ Root FWD 18 128.7 P2p
Desg FWD 19 128.50 P2p Fa0/5 Fa0/46 128.51 P2p Desg FWD 19 Fa0/47

Services1#show spanning-tree vlan 200

VLAN0200

Spanning tree enabled protocol rstp

Root ID Priority 24776 Address 0015.0

0015.c6c1.3000

Cost 37 Port 51 (FastEthernet0/47)

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Bridge ID Priority
Address 32968 (priority 32768 sys-id-ext 200)

0003.fd63.bb80

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Aging Time 300

Interface Role Sts Cost Prio.Nbr Type Altn BLK 19 128.7 P2p Fa0/5

```
Altn BLK 19 128.50 P2p
Root FWD 19 128.51 P2p
Fa0/46
Fa0/47
```

Services2#show spanning-tree vlan 100

VLAN0100

Spanning tree enabled protocol rstp Priority 24676 Address 0015.63f6.b700 Root ID

Cost 37
Port 42 (GigabitEthernet0/42) Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Bridge ID Priority 32868 (priority 32768 sys-id-ext 100)
Address 00d0.2bfc.7d80
Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Aging Time 300

Interface Role Sts Cost Prio.Nbr Type Altn BLK 19 128.6 P2p Root FWD 19 128.42 P2p Fa0/6 P2p Fa0/42 Fa0/43 Altn BLK 19 128.43 P2p

Services2#show spanning-tree vlan 200

VLAN0200

Spanning tree enabled protocol rstp

Priority 24776 Root ID 0015.c6c1.3000

Address

Cost 18
Port 6 (GigabitEthernet0/6)

Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Bridge ID Priority 32968 (priority 32768 sys-id-ext 200)
Address 00d0.2bfc.7d80
Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec

Aging Time 300

Role Sts Cost Prio.Nbr Type Interface ______ Root FWD 18 128.6 P2p Desg FWD 19 128.42 P2p 64.43 P2p Fa0/42 Desg FWD 19 Fa0/43

Troubleshoot

There is currently no specific troubleshooting information available for this configuration.

Cisco Support Community - Featured Conversations

Cisco Support Community is a forum for you to ask and answer questions, share suggestions, and collaborate with your peers. Below are just some of the most recent and relevant conversations happening right now.

Want to see more? Join us by clicking here Migration from PVST to Rapid-PVST delvauxra 2 Replies 6 years, 3 weeks ago Migration to Rapid PVST paul.kyte 5 Replies 4 years, 11 months ago spanning-tree backbonefast + rapid-pvst+ jason.fraioli 2 Replies 3 years, 20 hours ago spanning tree pvst or rapid-pvst SystemAdminNet 6 Replies 6 months, 1 week ago Spanning-tree modes: PVST vs RAPID-PVST <u>CanEHdian</u> 1 Reply 4 years, 5 months ago spanning-tree uplinkfast and rapid-pvst **smith.ward** 1 Reply 3 years, 11 months ago C6509 Spanning tree rapid-pvst+ anjery1234 1 Reply 1 year, 8 months ago spanning-tree mode rapid-pvst ???? trptplayer1 4 Replies 3 years, 7 months ago migration from rapid-pvst to mst pedroquiroga 2 Replies 5 years, 2 months ago

Rapid-pvst+ and spanning tree tuning. gacross 1 Reply 5 years, 6 months ago

Start A New Discussion

Subscribe

Related Information

- How to configure STP diameter in Cisco Catalyst switches
 Understanding Rapid Spanning Tree Protocol (802.1w)
 Spanning Tree Protocol Problems and Related Design Considerations
 Spanning Tree Protocol Root Guard Enhancement
 Understanding Multiple Spanning Tree Protocol (802.1s)
 LAN Product Support Pages
 LAN Switching Support Page
 Technical Support & Documentation Cisco Systems

Updated: Jan 12, 2007

Document ID: 72836

Contacts | Feedback | Help | Site Map © 1992-2010 Cisco Systems, Inc. All rights reserved. Terms & Conditions | Privacy Statement | Cookie Policy | Trademarks of Cisco Systems, Inc.