

Machine wash, Machine wash, permanent











Machine wash press

gentle or delicate



do not wash

water temperature not above: 30°C 40°C or 80°F

50°C or 105°F or 120°F

60°C or 140°F













water temperature not above: 70°C 95°C or 160°F or 200°F

30°C or 80°F

40°C or 105°F

50°C or 120°F

60°C or 140°F

70°C or 160°F

95°C or 200°F

do not wring



















bleach If needed





Non-chlorine bleach f needed

Tumble dry

Dry normal, low heat

Dry normal, medium heat

Dry normal, high heat

Dry normal, no heat





















Hang to dry



Dry flat

Drv In the shade

Do not dry

Do not tumble dry

Drv

any temp. steam

Do not iron



**MaxImum** temperature 110°C 230°F



Maximum temperature 150°C 300°F



Maximum temperature 200°C 390°F



No steam



Drvclean



Anv solvent



Any solvent éxcept tetrachlorethylene



solvent

only

wet cleaning







moisture





finishing

