



Service Engineering Operations
Customer Service Division

Ford Motor Company
PO Box 1904
Dearborn, Michigan 48121

February 10, 2026

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: **Recommended Repair Prior to Sale
Customer Satisfaction Program 26P02**
Certain 2025-2026 Model Year F-150 and F-250-600 vehicles
Driver Door Module (DDM) & Passenger Door Module (PDM) Software Update

PROGRAM TERMS

This program will be in effect through February 28, 2027, for vehicles within the new bumper-to-bumper warranty coverage period.

URGENCY / EXPIRATION DATE

This Customer Satisfaction Program has an expiration date of February 28, 2027, to encourage dealers and customers to have this service performed as soon as possible.

FSA VIN Lists are expected to be available on February 10, 2026.

AFFECTED VEHICLES (U.S. Population Of Affected Vehicles 413,904.)

Vehicle	Model Year	Assembly Plant	Build Date Range
F150	2025	Dearborn	June 10, 2025 through December 20, 2025
		Kansas City	June 10, 2025 through November 25, 2025
	2026	Dearborn	July 9, 2025 through January 9, 2026
		Kansas City	June 10, 2025 through January 9, 2026
F250-600	2025	Kentucky Truck	June 10, 2025 through July 22, 2025
		Ohio	June 10, 2025 through August 15, 2025
	2026	Kentucky Truck	July 7, 2025 through January 7, 2026
		Ohio	June 17, 2025 through January 12, 2026

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS PROGRAM

On some of the affected vehicles, the customer may experience a false window bounce-back from a fully closed position. If this occurs, customers will lose one-touch operation and may have difficulty closing the window and restoring one-touch up operation.

SERVICE ACTION

Customer satisfaction P-type programs are to be performed on impacted vehicles already in for other service work (either mobile repair or in dealership). Before delivering any in-stock vehicles involved in this program, dealers are recommended to update the DDM & PDM to the latest software version using FDRS. This service must be performed on all affected vehicles at no charge to the vehicle owner.

FSA PROGRAM OPTIONS

Program Option		Eligibility	Comments
Mobile Repair	Funded	No	See Mobile Service Capable Repair Assessment Level section below, if applicable.
	Capable	Yes	
Over-the-Air (OTA) Update		No	See Over-The-Air (OTA) Updates section of the FSA Policy Document, if applicable.
Rentals		No	See the Rental Vehicles section below, if applicable.
Alternative Transportation Available		No	See Alternate Transportation section in the FSA Policy Document.
Pickup & Delivery (PDL)		No	See Pickup & Delivery section in the FSA Policy document.
Towing		No	See Claims Preparation and Submission section below, if applicable.
Essential Special Service Tools (ESST)		No	See Technical Instructions and/or Workshop Manual (WSM) as needed.
Administrative Allowance		No	See Administrative Allowance section in FSA Policy Document, and if applicable, Labor Allowances table below.
Owner Refunds		No	See Owner Refunds section below, if applicable.
Photo Submission		No	See Repair Photo Submission section below, if applicable.

Note: For further information on certain Program Options above, see the corresponding section within the FSA Policy Document.

OWNER NOTIFICATION MAILING SCHEDULE

Owner letters will not be mailed for this program.

ATTACHMENTS

- Technical Instructions
- Mobile Service Repair Assessment

REFERENCE MATERIAL

- Warranty & Policy Manual (located on FMCDDealer Warranty Portal Page):
www.fmcdealer.dealerconnection.com/content/fmcdealer/us/en/parts_service/wty.html
- FSA Policy Document (located on FMCDDealer FSA Resources Page for Ford and Lincoln dealerships):
www.fmcdealer.dealerconnection.com/content/fmcdealer/us/en/parts_service/fsa/rsc.html
- FSA Policy Document (located on the Fleet SharePoint site for Fleets with in-house warranty):
<https://azureford.sharepoint.com/sites/OneWarrantySolution/usfleet/SitePages/Home.aspx>

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division

Customer Satisfaction Program 26P02**MOBILE SERVICE REPAIR ASSESSMENT LEVEL**

- Customer satisfaction P-type programs are to be performed on impacted vehicles already in for other service work (either mobile repair or in dealership) and Remote Experience reimbursement for just this repair is not allowed.
- All Vehicles Affected

 - Mobile Reprogramming (MRA1)

OASIS ACTIVATION

OASIS will be activated on February 10, 2026.

FSA VIN LISTS ACTIVATION

FSA VIN Lists will be available through <https://web.fsavinlists.dealerconnection.com> by February 10, 2026.

SOLD VEHICLES

- Correct affected vehicles identified in OASIS which are brought to your dealership within the applicable bumper-to-bumper warranty coverage period.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

STOCK VEHICLES

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

BRANDED / SALVAGED TITLE VEHICLES

Branded / salvaged title vehicles are eligible for this service action.

OWNER REFUNDS

Refunds are not approved for this program.

RENTAL VEHICLES

Rental vehicles are not approved for this program.

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSA's / Related Damage.
- **For modules not requiring an RVC, use normal diagnostics.**
- **For vehicles within new vehicle bumper-to-bumper warranty coverage, no SSSC approval is required**, although related damage must be on a separate repair line with the "Related Damage" radio button checked.
 - Ford vehicles – 3 years or 36,000 miles
- **For vehicles outside new vehicle bumper-to-bumper warranty coverage**
 - Submit an Approval Request to the SSSC Web Contact Site before completing the repair.

Customer Satisfaction Program 26P02

CLAIMS PREPARATION AND SUBMISSION

- **Technician Competency Requirement:** The STST Competency 10 certification requirement in the U.S. market only will be enforced starting with repair orders opened on or after August 31, 2024. FSA repairs will be rejected, and the claim will not be paid if the repairing technician is not certified in STST Competency 10 FSA. See EFC15936 for more details.
- **Software Verification Approval Code Requirement:**
This program is exempt from the Software Verification Approval Code Requirement.
- **Claim Entry:** Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - When entering claims:
 - Claim type 31: Field Service Action
 - Sub Code: 26P02
 - Customer Concern Code (CCC): G07
 - Condition Code (CC): 04
 - Causal Part Number: 14B291 Quantity 0
 - For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.
- **Related Damage/Additional labor and/or parts:** Must be claimed as Related Damage on a separate repair line from the FSA with the same claim type and subcode as described in Claim Entry above.

IMPORTANT: Click the Related Damage Indicator radio button.

Customer Satisfaction Program 26P02

LABOR ALLOWANCES

Description	Labor Operation	Labor Time Hour(s)
Install latest driver door and passenger door module software using FDRS. This labor operation code closes the FSA.	26P02B	0.4

PARTS REQUIREMENTS / ORDERING INFORMATION

Parts are not required to complete this repair.