

Engineering Tool Request

Date: June 17, 2025

Request No.: ETR-2025-082

Engineer: J. Doe

1.0 Referenced Documents

Drawing Number	Revision	Title
C-WK061725-D1	A	COWL ASSEMBLY AND FASTENER LOCATIONS

2.0 Scope

This request provides specific instructions for drilling operations on part number **Cowl_WK061725**, as detailed in the referenced drawing and visual aids.

3.0 Instructions

3.1 Bottom Section Drilling (Yellow Marker)

- Operation:** Drill through holes.
- Hole Diameter:** 0.500"
- Locations:** Drill the **first ten (10)** fastener locations only, starting from the designated origin point in the area marked with yellow. DO NOT DRILL HOLES ANNOTATED WITH RED BOX

3.2 Top Section Drilling (Blue Marker)

- Operation:** Drill through holes.
- Hole Diameter:** 0.625" (5/8")
- Locations:** Drill all fastener locations in the area marked with blue **EXCEPT** for the **last five (5)** holes in the sequence.
- Exclusion:** **DO NOT** drill the final five fastener locations in the top row as annotated by the red box

4.0 Approval

Requesting Engineer:

J. Doe

Manufacturing Supervisor:

(Signature)