## **Top Notch Motors Inc.**

264 Queen Street E. Brampton ON L6V 1B9

www.topnotchmotors.ca goodyeartopnotch@gmail.com

Tel.#: (905) 459-2050 Fax: (905) 459-2808

BHADRESH MODI BHADRESH MODI 44 Donwoods Crt BRAMPTON, ONT L6P1T6			Plate:	.N.: 1G3NR52T41C252676			# :88723 :11/20/2020 : : # :878819929RT0001		
H#:416	#:416 716-7782 B#:		Engine:	2.41	Tech.	: TEMP/			
Qty	Hrs.	Description		Parts Ea.	Tot.Parts	Labour	Tx :	<b>Total</b>	C
1.00		diagnose engine light					HST		
1.00		belt squeal					HST		
1.00		reset oil light not do	one last				HST		
		service					HST		
	1.50	computer scan tested recorded				147.00	HST	147.00	
		and decoded codes, ins	stalled				HST		
		new gas filler neack					HST		
1.00		Fuel filler neck		90.00	90.00		HST	90.00	
1.00	1.00	diag, and removed a/c	clutch			98.00	HST	98.00	
		causing belt noise and	i				HST		
		draging					HST		
1.00		Environmental Fee		1.50	1.50		HST	1.50	

WO# 108038 Copyright 2021 Autogence Inc. - LANKAR 11.13.I

## IT IS THE CUSTOMERS RESPONSIBILITY TO RETURN WITHIN 100 KM FOR RE TORQUING OF WHEELS WHEN REMOVED FOR WORK PERFORMED

PAID BY:... 11/20/2020 Amex 380.25

This company does not assume any responsibility whatsoever for vehicles or other equipment left for repairs or storage or for articles left in vehicles or equipment. Vehicles driven by our employees at owner's risk.

In the event of non-payment of the said total charge, the owner authorizes this company to repossess the vehicle or article and hold it until this total bill is paid or sell it.

I hereby authorize the above work to be completed:

Customer Signature / Initials: \_\_\_

### 91.50 245.00 336.50

### 43.75

### 0.00

### 0.00

### Deductible 0.00

### Total 380.25

Page

1 of 1