

WestCall DEFINING Innovation © XCEEDING Standards + LADING The Nurse Call Industry

2200 Cordelia Road, Fairfield, CA 94534

To: Jack Kelly From: Jack Kelly Date: Dec 17, 2018

Subject: DeBug Log for Explorer HAT Test Fixture Rev P1 to Rev A

- 1. C1 GND not connected
- 2. U11 change from 07 to 06
- 3. R16 change from +3.3V pull-up to R16 to GND
- 4. R8 changed from 54.9K to 59K (+3.5V output was low)
- 5. U10 changed from 06 to 07
- 6. U3 changed from LCB710S (NC) to LCA715S (NO)
- 7. Add Cap 10uF 10V across J3

DeBug Log Page 1 of 1