https://www.ti.com/lit/ug/slau825/slau825.pdf
Wiring instructions(Power into DAC, DB25 to DAC, DAC to FSM)

Desolder C1 - C4, C14-C17, they slow down signal speed.

Data input diagram:




Figure 7. LaunchPad™ Interface Pinout

Board wiring:

