

TITLE : Process Flow Chart for PCBA Process Instruction**REVISION HISTORY**

Rev.	Description of Changes	Issued by	Date
P1	Initial Release (refer ECN No.2208-0011)	Yutthakarn P.	Aug 01,22
A	Add Process flow for clean model (refer ECN No.2302-0025)	Yutthakarn P.	Feb 24,23
B	Revise process name in item 2.1 and 2.2 (refer ECN No.2304-0044)	Yutthakarn P.	Apr 10,23
C	Add PCBA routing process (Opn.90) (refer ECN No.2402-0017)	Yutthakarn P.	Feb 06,24
D	Add Vacuum Pressure Oven & AOI Inspection and update PI No. of AOI both no cleaning and cleaning process and change Number Process (refer ECN No.2501-0053)	Yutthakarn P.	Feb 06,24
E	Revise process item 2.1 OPN. 105, 165 Revise Process Item 2.2 OPN.105, 175 (refer ECN No.2504-0018)	Tarnison Y.	Apr 09.25
F	Add Item 2.3 Process flow for no DSP /Flip chip model Item 2.1 revise name OPN#30, Item 2.2 revise name OPN#30 (refer ECN No.2507-0011)	Yutthakarn P.	Jul01 25
G	Remove Item 2.1 from model was EOL Add Item 2.3 Process flow for assembly part on 2 sides (Top and Bottom) have DSP/ Flipchip component , Topfill and underfill 2 side and cleaning process (refer ECN No.2511-0010)	Patcharin C.	Nov 06,25
H	Addition Item 2.4 PCBAs with components assembled on both the top and bottom sides, including PICs components Revise process flow item 2.1, 2.2 and 2.3 swap the process flow between laser mark barcode and Bad mark label and Kapton tape laminate.(refer ECN No.2607-0004)	Patcharin C.	Jul 01, 26


TITLE : Process Flow Chart for PCBA Process Instruction


1.0 PURPOSE

1.1 To provide the process flow chart for PCBA Product Process Instruction.

2.0 FLOW CHART

2.1 In case of PCBA have assembly part on 2 sides (Top and Bottom) and DSP/Flipchip component and **cleaning process**




TITLE : Process Flow Chart for PCBA Process Instruction
2.2 In case of PCBA have assembly part on 2 sides (Top and Bottom) and No DSP/Flipchip component and cleaning process

Symbol Key

○ = Operation X = Normal Operation
 □ = Inspection O = Sampling, Special case

TITLE : Process Flow Chart for PCBA Process Instruction

2.3 In case of PCBA have assembly part on 2 sides (Top and Bottom) have DSP/ Flipchip component, Topfill and underfill 2 side and cleaning process




Symbol Key

○ = Operation X = Normal Operation

□ = Inspection O = Sampling, Special case

TITLE : Process Flow Chart for PCBA Process Instruction

2.4 In the case of PCBAs with components assembled on both the top and bottom sides, including PICs components, perform the cleaning process on both sides.



Symbol Key

○ = Operation X = Normal Operation

□ = Inspection O = Sampling, Special case