Possibility of Paper Jam due to the failure of Tandem Paper Feed UNIT

The overlapped area between the paper feed roller and separation roller becomes less due to the warp of the upper frame of Tandem paper feed, which may cause the center of the paper being bent or may cause the paper jam. (Tray3 or Tray 4 Jam)



Tandem Paper Feed for Phoenix















