VOLVO



| MODEL | GROUP | NUMBER |
|---------------------|---------|--------|
| 200/700-900 | 28 | 102X |
| | TITLE | |
| UPDATE TO SB | 28-102: | |
| | | |
| DATED MAY 199 | 14 | |
| DATED MAY 199 | 14 | |
| DATED MAY 199 |)4 | |
| DATED MAY 199 |)4 | |
| DATED MAY 199 | T | DATE |

Page 1 of 1

THE FOLLOWING INFORMATION SHOULD BE ADDED TO SB 28-102; DATED MAY 1994, THIS SERVICE BULLETIN SHOULD THEN BE DISCARDED.

On the application chart on page 4, add P/N 5003786-0 (in addition to P/N 3517368-1) under the heading Engine Type B230FT (EGR), Existing MFI LH2.4 Control module in vehicle.

Index *

039299

Service Personnel: circulate, read, and initial.

| SERVICE | SHOP | SERVICE | SERVICE TECHNICIANS |
|---------|---------|---------|---------------------|
| MANAGER | FOREMAN | ADVISOR | |
| | | | |

Printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste.
© 1994 VOLVO CARS OF NORTH AMERICA, INC.