

1

2




3

4

5

Replace resistor 1k2

Solder on 6k8




Remove 121 Resistor
Solder A jumper

8 Hours

4 Hours

20 2 Hours

10 1 Hours



8 Minutes

40 4 Minutes

20 2 Minutes

10 1 Minutes

TITLE:

Sheet_1

REV: 1.0