SUPERSEDES:

none

## HP MODEL 6012A AUTORANGING POWER SUPPLY Serial Numbers 2116A00300 and Below NEW FAN INSTALLATION HARDWARE

Tubeaxial fan B1 has been changed from HP Part No. 3160-0328 to HP Part No. 3160-0301. When installing the new fan use 4 6-32 machine screws HP Part No. 2370-0026 along with 4 6-32 sheet metal nuts HP Part No. 0590-0653.

The old hardware, 6-32 flathead screw HP Part No. 2360-0388 and hex nut with lockwasher HP Part No. 2420-0006, cannot be used to mount the new fans and should be used if replacing the old fan with a similar type.

E/OF/WO

10/81-21/JY



FOR MORE INFORMATION, CALL YOUR LOCAL HP SALES OR SERVICE OFFICE or East (201) 265-5000 ● Midwest (312) 255-9800 ● South (404) 955-1500 ● West (213) 970-7500 or (415) 968-9200; OR WRITE, Hewlett-Packard, 1501 Page Mill Road, Palo Alto, California 94304. IN EUROPE, CALL YOUR LOCAL HP SALES or SERVICE OFFICE OR WRITE, Hewlett-Packard S.A., 7, rue du Bois-du-Lan, P.O. Box, CH-1217 MEYRIN 2 - Geneva, Switzerland. IN JAPAN, Yokogawa-Hewlett-Packard Ltd., 9-1, Takakura-cho, Hachioji-shi, Tokyo, Japan 192.