

Vehicle Inspection Report
Unit V-183 : 2023 Ford Transit 350

Inspection date: 2024-10-29 09:45 UTC
Performed by: Eastport Fleet Maintenance
Case: FSI-2024-00312

Incident context

Unit V-183 made low-speed rear contact with a stationary forklift near Bay 4.
Dashcam metadata records 4.2 mph at point of contact. No injuries reported.

Findings

- Bent trailer hitch receiver, non-safety critical.
- Minor scratch on rear lower valance.
- Rear bumper scuffing consistent with forklift counterweight contact.
- No cargo bay door intrusion or structural deformation observed.
- Lights, brakes, reverse alarm, and safety systems operational.

Disposition

Vehicle cleared for continued operations pending cosmetic repair.
Estimated repair cost: \$380.

Maintenance note

Document retained for fleet safety review and corrective-action traceability.