

Inspection Brief

Hargrove Building A

CASE	SIR-2024-00091
SITE	Building A : 1140 Eastside Blvd, Unit Campus
REQUESTED BY	Hargrove Commercial Properties
SUBMITTED	November 4, 2024
SCOPE	Exterior envelope assessment ahead of winter season

Client Concern

Property management reported recurring damp patches in the Level 1 northeast corridor and visible facade cracking noticed by tenants.

The requested assessment focuses on the exterior envelope, roof edge, window head conditions, ground plane, and entry transitions.

Known Areas For Review

- North parapet flashing and sealant condition.
- Level 2 masonry spandrel crack between window columns C and D.
- Southeast corner staining and possible window head flashing failure.
- Back entrance threshold and accessible route transition.

Requested Output

Provide a structured field report with photos, annotated spatial findings, prioritized remediation actions, and evidence references suitable for owner review.