



Manheim Ohio 3905 Jackson Pike Grove City, OH 43123-9300 (614) 871-2771

Moon Roof

110,681

VEHICLE DETAILS

2003 BMW X5 4.4L

VIN: 5UXFB33563LH45935 EXT COLOR/Code: TITANIUM

1521124 FINANCIAL SERVICES Seller:

REMARKETING (LEASE)

Body Style: 4CUV INT COLOR/Code: GRY Lane Number:

Inspector: JBROWN2 05/06/2009 Rcv Date: 05/06/2009

VEHICLE IMAGES



Work Order #:











GRADING



Top Type:

Run Number: 289

Mileage:

Grade 3.4 Average More About Auto Grade

Certified - No Drivable - Yes

VEHICLE INFORMATION

OPTIONS

- Pwr Lock
- Tilt Steering
- Cassette Tape
- Power Folding Mirrors
- Trip Counter
- Cold Weather Package
- Security System
- HomeLink
- ST Steptronic
- Transmission Tire Pressure Monitor
- Power Seats Dual

Pwr Steering

- A/C
- Side Air Bags
- Owner's Manual
- CD Changer 6.00
- On-Board Computer
- Steering Wheel Audio

Control

- Premium Package
- Memory Seat Power Telescopic
- Heated Seats Front

- Pwr Window
- Cruise Ctl
- Dual Air Bags
- Premium Stereo DSP
- Rear Wiper
- US EPA Label
- Dual Air Conditioning
- Sport Package
- Woodgrain Interior

Package

Navigation System

- Pwr Seats Both
- Rear Defrost
- Power Mirrors
- Fog Lamps
- Power Trunk/Liftgate
- DSC-Dynamic Stability

Control

HDC - Hill Descent

Control

- Heated Seats
- Rain Sensor
- Directional Stability
- Control

MECHANICAL

- 8 Cylinder Gas
- Automatic
- AWD
- Pwr Brakes
- 4.4 L

INTERIOR

- Odometer 6 Digits Digital Operable
- Clean
- GRY Leather
- Int Odor: OK
- Wood Trim Dash

TIRES AND WHEELS

Tire Condition:	e Condition: Average		Alloy	
Tire	Tread Depth	Brand	Size	
Left Front:	6/32"	MICHELIN	255/55R18	
Left Rear:	5/32"	MICHELIN	255/55R18	
Right Front:	8/32"	MICHELIN	255/55R18	
Right Rear:	4/32"	MICHELIN	255/55R18	
Spare:	0/32"	MICHELIN	255/55R18	

KEYS

Master Key - 1

ADDITIONAL INFORMATION

SPT/PREM,DSP,HS,NAV,WT,CWP *BK, AS-IS CLEAN CARFAX 5/28/09

Common Abbreviations

DAMAGES - SUGGESTED REPAIRS									
Suggested repairs are based on Manheim professional inspector's recommendation.									
Total labor hours include paint, body or repair estimates.									
			SUGGESTED		TOTAL LABOR				
DESCRIPTION	CONDITION	SEVERITY	REPAIR		HOURS				
Front Bumper	Mult Scratches	1" to 2"	Airbrush		1.00				
Hood	Prev Repair	Acceptable	No Action Required		.00				
LF Fender	Prev Repair	Acceptable	No Action Required		.00				
LF Door	Dent/No Paint Dmg	PDR/1	PDR		.00				
LR Door	Dent/No Paint Dmg	PDR/1	PDR		.00				
Lift Gate	Dent/No Paint Dmg	PDR/1	PDR		.00				
RF Fender	Prev Repair	Acceptable	No Action Required		.00				
RF Wheel	Mult Scratches	1" to 2"	Repair		2.00				
RF Door	Dent/No Paint Dmg	PDR/1	PDR	TOTALS	.00				
				IUIALS	3.00				
		Print							

VIN: 5UXFB33563LH45935, Work Order #: 1521124