Manheim Post Sale Inspection Checklist

14:17:04

Vehicle Information Run#: 2008-008-92-0001 Vr/Mk:2001 BMW Model: X5 4.4L Yolor: White		Customer Information Dealership5230120 MAKMAL NORTH AMERICA CO Contact: Telephonc416-834-9505 Fax: 647-435-5876				Notes			
						Sale price: \$14,700			
							<u></u>	·	
4iles: 109,500 /IN: WBAFB33551LH13165		Info:				<u> </u>			
fundamental control of the control o		Bomorke: From DY: dl	r# - 51498	H; wo# · 000000	00		. mr. av OD	C. N	
Opts: ENG: 8G R: N	N TRN: A	PB: X AC: Y EW: X	ES: X TO	P: NO CC: X E	L: X INT: I			5: N	
Vehicle Inspectio		PSI		REQUI	ESTED	7-DAY GUARANTEE			
OK N/A Co	ncern (Check Points		Comment					
×									
									
_									
						· - ·			
								<u></u>	
		· · · · · · · · · · · · · · · · · · ·							
		· .				<u> </u>			
-							<u> </u>		
							<u> </u>		
_ -						·	W		
									
						<u>-</u>			
A-hitrotable Ita	me Found	d? □ Yes 및 No							
Ar bur acable 11e. Frame Check	Ma Louin	u. □ 1es ,az, 10							
	ncern	Comment							
General Comments	ii.	`	Fram	e Inspection					
become	Paent	4700TY 6	D No A	Apparent Visible	Damage 🔲	Frame / Structur	al Damage (see	below)	
				1	De L	adder Frame			
	commenda	tions		≪		_		Frant frame rall	
			dy Structul	rai Parts	THE STATE OF THE S	747	P==	Spring Pod	
	 				ear strut Tower	¥	4 19-	Mam crops medibat Torque bos	
Requested	Complet	ed Lasm P	Cowl and/Firewsii	A-Pillor	<u> </u>	~		Transmissian suppo	
Date: 2/14/2009	Inspector:	Q: W1	1	J D	₽		◆-	Front side rail	
Date: 2/14/2008	Date:	Strui To			№ № -166	<u>.</u>			
Time: 14:17:03	Time:	<u> </u>						Gegr summension	
Seller Information					- B. Piller	(all	@ -	— Gross Rember - Habi goring pod	
5149811 SOVEREI Phn: 810-487-2020		PURCHASING L L -487-2022			The state of the s	PERIMETÉA FRAME	∥ ∥⊷	— Near framerall	
F1M1, 01V-40/-2U2U	1 ax. 610	F	Redietor Core	Front Rall	Rocker Fanel		<u> </u>	Roar cross mambe	
		:	Support	•	1 111111				