Pass: X Yes No

X 7-Day 14-Day

| Run #: 2011-041-07-0103 | VIN: JHLRD78842C030413 | M2C03 | 0413 | Dealership: 5230120 MAKMAL NORTH AMERICA CO | | i Inspect | <u>§</u> | Type of Inspection: FRANC MECH SEFULL |
|--|------------------------|----------|----------|---|--|-----------------------------|--------------|---|
| Hork Order #: 1933511 | YIMK: 2002 HONDA | NOA | | Contact: 01 - VALENTINA SHEVCHIK | | Inspection Date: 10/13/2011 | 1 | |
| | Model: CR-V | | | Phone: 416-840-5849 Fax: 647-435-5876 | Signer: 416-834-9505 | ons Prope | ∛ | Functions Properly: 🛛 YES 🔲 NO |
| Simukast Sale: ☑ YES ☐ NO | Color SILVER | | | Announcements: | | ECR Verified: | | TES INO |
| Odometer IN: 153678 | Odomeler Out 153678 | 53678 | | | | | 1 | |
| Comments | | Pass | Fai⊢ | | Comments | P | | |
| ODOMETER | | | | | SRS (Supp Restraint System/Air Bags) (Continued) | ∰ 400 400 | | |
| ENGENE | | | | | | × | | Any indicators of Damage to Airbags or |
| | | × | | Engine Light On | THANSINSSION | | | |
| | | × | | Fuel System | | × | | Operates Properly |
| | | <u> </u> | | engine Block | | × | | Abnormal Noise |
| | | < > | | Engine Mouni | | × | | Leaks |
| | | × > | | Engine Operation | ACCESSORIES (Electrical) | | | |
| | | × | | Fluid Levels | | z | > | Power Seals Functioning |
| | | × | | Leaks | | × | T | Power Windows Functioning |
| | | × | | Engine Studged | | : × | | Power Locks Functioning |
| | | × | | Power Steering System Functioning | | \ \ \ | T | Hadio, Video, Audio Operates Normally |
| ATSIEM OPENABLE | | | | | | z : | P | Power Ton Onevales Property |
| | | 2 | ┖ | Abnormal Noise | | z | >- | Navigation System Functions Property |
| RSHRAKES | | 2 | 2 | Engages Properly | PAINTWORK INSPECTED | | _ | |
| | | 1 | ┖ | | | × | | Visible Signs of Paintwork |
| | | × | | Brakes Function Propody | FLOOD DAMAGE | _ | _ | |
| | | × | | ABS Light On | | × | | Any Components Damaged Due to |
| | | × | | | | × | | Any Other Indicators of Flood Damage |
| MISSION CONTROL EQUIPMENT | ENT | | | | FHAME OR UNBODY STRUCTURAL DAMAGE | | | |
| | | × | | Calalytic Converter Present | | × | | Visible Frame Rail Damage |
| | | × | L | Crank Case Ventilation Issue | | < > | | Cross Member Damage, Repaired or |
| 5 5 5 5 5 5 5 5 | | × | | Engine Modification | | | 1 | Aprons, Upper Heinlordement Hall Damage |
| | | × | L | Warning Light On | | , | Ţ | Darker Brasil Componential State (A,B,C |
| 000000000000000000000000000000000000000 | | × | Ļ | Oxygen Sensor Issue | | × > | | Floor Panels Tom Perforated or Rendered |
| C COMPRESSOR ENGAGEMENT | ENT | | L | | | × > | | Overler Panel or Cab Panel Booksood |
| | | × | _ | Ooes Vehicle Have AC | | × | | Frame or Unificaty Altered |
| | | × | | Is AC Operable | | | | |
| 11 15 15 16 | | × | <u>_</u> | Switches on and off normally | | | | |
| 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | | × | _ | Any Irregular Noises | | | | |
| | | × | _ | Leaks | | _ | | |
| | | × | L | Irregular Condensation Around AC | | • | | |
| HS (Supp Hestraint System/Air Bags) | ir Bags) | | L | | | | | |
| 02 INTERNAL SAS MODULE MALF | 71 | _ | × | Indicator I amo Illuminatas I Iron Starting | | | _ | |

Phone: 703-448-0100

Fax 571-379-4685

Top Side Inspector, GLINDEN
Frame Inspector, JULLERY Test Drive Inspector: DCARNILL Test Drive: 120 YES 1 NO

Setter: 5063866 TYSONS FORD INC