EI MECH MA FULL

🗶 7-Day 🗌 14-Day

Pass: XYes 🕦 No

Run# 2011-050-92-0006	VIN: JTJHT00W143537055	Daaleiship: 5230120 MAKMAL NORTH AMERICA CO	Type of Dispection:
Work Order # 6037764	YUM: 2004 LEXUS	Contact VALENTINA SHEVCHIK	Inspection Date: 12/12/2011
Sale Date: 12/12/2011	Model: LX470	Phone: 416-840-5849 Fax: 647-435-5876 Signer: 416-834-9605 Functions Property: \$2 TES INO	Functions Property: X YES NO
Simulcast Sale: TYES 🖾 NO	Color. GRAY	Announcements:	ECR Verified Types (S) NO
Odometer IN: 132429	Odometer Cut: 132429		

Comments	Pass	Fail		Conuments	Pass Fail	
ODOMETER				SRS (Supp Restraint System/Alr Bags) (Continued)	(Pan	
ENGINE					×	Any Indicators of Damage to Airbags or
	X	_	Engine Light On	TRANSMISSION		
	×		Fuel System		×	Operates Property
	×	_	Engine Block		×	Abnormal Noise
	×		Engine Mount		×	Leaks
	×	_	Engine Noise	Accessonies (Electrical)		
	×	7	Engine Operation			Omers Conta Constitution
	X	-	Fluid Levels		< < >	ruwei oeats ruixipolitig
	×	-	Leaks		ζ,	Power windows Functioning
	×	Ī	Engine Sludged		× ;	Power Locks Functioning
	×	Ī	Power Steering System Functionand		×	Radio, Video, Audio Operales Normally
4X4 SYSTEM OPERABLE					× ;	Power Sunrool Operates Property
	×		Abnormal Noise		< >	Neuroston Sucton Supplies Denotes
	×	Ī	Engages Property	DAINTWOOK INCOCETTED		friedor of stem all choice a robotic
ABS/BRAKES					 	Meiha Sione of Baintunds
	×	<u> </u>	Smooth Pedal Operation	EL COOL DAMAGE	:	
	×	3	Brakes Function Property		;	
	×	1	ABS Light On		× :	Any Components Damaged Live to
	×	Ξ	Leaks		×	Any Other Indicators of Frood Damage
EMISSION CONTROL EQUIPMENT				FRAME OR UNIBODY STRUCTURAL DAMAGE		
	×	ľ	Catalytic Converter Present		×	Visible Frame Rail Damage
	×	Ĭ	Crank Case Ventilation Issue		×	Cross Member Damage, Repaired or
	×	T	Engine Modification		×	Aprons, Upper Reinforcement Rail Damage
	×	^	Warning Light On		×	Damage to Roof Support Pillars (A,B,C
	×	٦	Oxygen Sansor Issue		×	Rocker Panel Damaged, Repaired or
AIC COMPRESSOR ENGAGEMENT		1			×	Floor Panels Tom, Perforated or Replaced
	,	†			×	Quarter Panel or Cab Panel Replaced
	< ;	7	LOGS VEHICLE Have AC		×	Frame or Unibody Allered
	×	-	Is AC Operable			
	×	S	Switches on and off normally			
	×	*	Any Inegular Noises			
	×		Leaks			
	×		Imagular Condensation Around AC			
SRS (Supp Restraint System/Air Bags)						
	×	_	Indicator Lamp Illuminates Upon Starting			

Select 0981772 BARCAR MOTORS Phone: 952-938-4800 Fax

MSC12122011/162254

PA PA

Additional Comment. AIR RIDE SYSTEM WORKING PROPERLY



Test Drive Inspector CPHILLIPSZ Test Drive: IX YES ☐ NO

Top Side Inspector. CPHILLIPS2 Frame Inspector: CPHILLIPS2