FROM BAY CITIES 14 2008 15:16/ST.15:16/No.7523561055 P **Manheim Post Sale Inspection Checklist** 19:00:38 Vehicle Information **Customer Information** Notes Sale price: \$10,800 Run#: 2008-033-03-0099 Dealership5230120 MAKMAL NORTH AMERICA CO Yr/Mk:2001 MERCEDES Contact: 01 - VALENTINA SHEVCHIK Model: E320 Telephone416-834-9505 Signer: 416-834-9505 Color: SILVER 647-435-5876 **CASH** Miles: 75,340 Info: VIN: WDBJF65J41B264821 AnnounceGL ** SOLD ON SIMULCAST ** Lights: GRN Remarks: Opts: ENG: 6G R: T TRN: A Vehicle Inspection **POST SALE INSPECTION - FULL** REQUESTED 7-DAY GUARANTEE OK N/A Concern **Check Points** Comment ENGINE (INCL. DRIPPING OIL LEA TRANSMISSION DIFFERENTIAL TRANSFER (4X4, AWD) **EMISSION CONTROL EQUIPMENT** A/C SYSTEM (CALENDAR YR OR NEW, **ODOMETER** ABS SRS (SUPP RESTRAINT SYSTEM) Pour Wandowhi ACCESSORIES (ELECTRICAL) PAINTWORK 3 PANELS OR MORE (CU. FLOOD DAMAGE FRAME OR UNIBODY STRUCTURAL DA Arbitratable Items Found? ☐ Yes Frame Check Concern Comment Seneral Comments: Frame Inspection ✓ No Apparent Visible Damage ☐ Frame / Structural Damage (see below)

Reconditioning Recommendations Requested Completed Inspector: Date: 8/13/2008 Date:


19:00:38 Time: Time:

Seller Information

5046240 CALIFORNIA AUTO WHOLESALE

Core

Phn: 510-783-3399 Fax: 510-783-3311



Rocker Panel

Manheim Post Sale Inspection Checklist

9:28:49

H/C

Vehicle Informati	on Customer	Intormation		Notes			
Run#: 2008-033-94-00	Dealership 523	Dealership 230120 MAKMAL NORTH AMERICA CO			Sale price: \$14,750		
Yr/Mk:2005 BMW Contact:		5-834-9505 7-435-5876	**CASH**	Work order: 3217319			
VIN: WBXPA934X5 Lights:	WD18913 AnnounceHS; Remarks: Fro	m DX: dlr#: 4905102;	2008-034-24-0069	LK 4X4: A TL: X SRS: D SI: E	3 DF: X Emis: 5 Alt: N		
Vehicle Inspection		INSPECTION - FUL	=	7-DAY GUARANT	TEE		
OK N/A Cone			Comment				
	ENGINE (INCL. DE	RIPPING OIL LEA _	· m - m				
	TRANSMISSION	-					
\\	DIFFERENTIAL	_					
\	TRANSFER (4X4, /	AWD) _					
λ	EMISSION CONTR	OL EQUIPMENT _					
<u> </u>	A/C SYSTEM (CAL	LENDAR YR OR NEW_					
<u> </u>	ODOMETER	_1	66903		W		
<u> </u>	ABS	_					
<u> </u>	SRS (SUPP RESTR	AINT SYSTEM)			· · · · · · · · · · · · · · · · · ·		
X	ACCESSORIES (EL	ECTRICAL)					
	FLOOD DAMAGE	_					
		DV CTRUCTURAL DA					
Arbitratable Item		No		· · · - · · · · · · · · · ·			
Frame Check	, , , , , , , , , , , , , , , , , , ,						
OK Conce	ern Comment						
Seneral Comments:		Frame	Inspection		· · · · · · · · · · · · · · · · · · ·		
 		_ No Ap	parent Visible Damage	Frame / Structural Dan	nage (see below)		
		-		Ladder Frame			
Reconditioning Recon	nmendations	-			Frant frameral		
		- Unibody Structural	Bree eterri		Spring Pod Nain cross member		
Requested (Completed nspector:	Gowi Pane/Firewall	C-Pillar Rear strut Tower		Tarque lax Transmission support		
Date: 8/12/2008 [Date:	Strut Tower/	D (II)	Raer	frant side roil		
ime: 9:28:09	Гіте:	Apron		Lock Pillar	4		
Seller Information				- Rear Rail	Rear suspension cross member		
	. SERVICES REMARK ^F ax:	LETING	B-Pilk	PEPIMETER FRAME	Rear frame risk		
	· 	Radiator Fr Core	ont Rail Rocker Panel	<u></u>	Rept cross member		