	
ORDER ID OR LOAD VIN	3938 TTSBT20XX50073938
	ALODIO ON POOL OF IN
YEAR	2005
MAKE	Lexus
MODEL	Gn 4170
COLOR	alite
LICENSE NUMBER	
MILEAGE	

Sobox ENERGISES TWOAMOUNT DUE
UPON
DELIVERY OR
PICKUP


H-hairline S-Scratch PT-Pitted T-Torn B-Bent GC-Glass Cracked M-Missing SM-Smashed R-Rusty CR-Creased S-Scratched ST-Stained BR-Broken D-Dented RC-Rock Chip FP-Faided Paint

BILL OF LADING/VEHICLE CONDITION REPORT MEYER TRANSPORT MC#729251 3908 PENSACOLA DR. USDOT#2089970 LANTANA, FL 33462

OFF: (561) 433-0135 FAX (561) 433-0135 CALL FIRST

ORIGIN SHIPPER	Orlando Contral
ADDRE88	9800 Back man Rd
CITY	orlando ·
8TATE/ZIP	FC 32824
HOME PHONE	
WORK PHONE	

RECEIVER DESTINATION	W 8 Shipsing
ADDRESS	8-Autation Ct
CITY	Savannah
STATE/ZIP	GA 31408
HOME PHONE	
WORK PHONE	FAX 6417-435-5876



CIRCLE IF INCLUDED: BOOKS, KEYSTREMOTES, FLOOR-MATS, ANTENNA, TITLE

COMMENTS SCIONARIOS - Dends Joseph Fendes Rock mivors Run

buper toulgente Buskrpand which elibra

BE SURE TO INSPECT YOUR VEHICLE THOUROUGHLY BEFORE SIGNING THIS REPORT. PLEASE NOTE THAT DURING TRANSPORT, VEHICLES AND COMPONENTS MAY CEASE TO OPERATE PROPERLY THROUGH NO FAULT OF THE CARRIER. THE CARRIER WILL ONLY BE RESPONSIBLE FOR EXTERNAL DAMAGE CAUSED BY THE HAULER. THE CARRIER ASSUMES NO LIABILITY FOR ANY ITEMS LEFT IN THE VEHICLE DURING TRANSPORT. DID NOT SEE ANYTHING UNUSUAL, OR CRIMINAL OR ILLEGAL IN VEHICLE ON PICK UP.

THE CUSTOMER'S SIGNITURE AT ORIGIN INDICATES	THE CUSTOMER'S SIGNITURE AT DESTINATION INDICATES THIS				
AGREEMENT WITH THE HAULER'S ASSESSMENT OF THE	VEHICLE WAS RECEIVED IN GOOD CONDITION EXCEPT AS NOTED				
CONDITION OF THIS VEHICLE.	ABOVE, THEREBY RELEASING THE CARRIER FROM ANY				
	ADDITIONAL LIABILITY.				
AUTHORIZED HAVILER / TIME DATE	AUTHORIZED HANULER / /// TIME DATE				
3 (Kanbs Algre 6-1812	5 / Marco 1/2 30160/4/2				
A SHIPPER SIGNITURE DATE	RECEIVER SIGNITURE				
 	(E C) 6/19/1/2				
CHIPPER PRINTER	T DECEMED PRINTED				
SHIPPER PRINTED	S RECEIVER PRINTED				
<u> </u>	- HUG COUTEDUCE				

ORDER ID OR LOAD	7345
VIN	3 T 38T20X470137345
YEAR	<i>9</i> 007
MAKE	Lexus
MODEL	B>470
COLOR	white
LICENSE Number	
MILEAGE	

	terolises the
AMOUNT DUE	app DOSKA
UPON	0.00
DELIVERY OR	
PICKUP	


H-hairline S-Scratch PT-Pittad T-Torn B-Bent GC-Glass Cracked M-Missing SM-Smashed R-Rusty CR-Creased S-Scratched ST-Stained BR-Broken D-Dented RC-Rock Chip FP-Faided Paint

BILL OF LADING/VEHICLE CONDITION REPORT MEYER TRANSPORT MC#729251 3908 PENSACOLA DR. USDOT#2088970 LANTANA, FL 33462

OFF: (561) 433-0135 FAX (561) 433-0135 CALL FIRST

ORIGIN SHIPPER	Manhagen Central
ADDRES8	9800 Bodymen Rd
CITY	ortando
STATE/ZIP	FC 30224
HOME PHONE	
WORK PHONE	·

RECEIVER DESTINATION	W8 Shipping
ADDRESS	& Aviertion Ct
CITY	Savannous
STATE/ZIP	C-A 31408
HOME PHONE	727-239-9590
WORK PHONE	



	_
CIRCLE IF INCLUDED: BOOK\$, KEYS, REMOTES) FLOOR-MATS, ANTENNA, TITLE	- 1
	- 1
	\dashv
COMMENTS Scrabelies + Deuts closers hard factors roof invorce	7
- SCHEMENT 11800 COST 1800 1800 1800 1800 1800 18	ረዋኅ
Dupor tempente Quetepourot Winshidd Broken	-/
Dupa Tallowe (Suche Dullow Winshillon 1500 con	

BE SURE TO INSPECT YOUR VEHICLE THOUROUGHLY BEFORE SIGNING THIS REPORT. PLEASE NOTE THAT DURING TRANSPORT, VEHICLES AND COMPONENTS MAY CEASE TO OPERATE PROPERLY THROUGH NO FAULT OF THE CARRIER. THE CARRIER WILL ONLY BE RESPONSIBLE FOR EXTERNAL DAMAGE CAUSED BY THE HAULER. THE CARRIER ASSUMES NO LIABILITY FOR ANY ITEMS LEFT IN THE VEHICLE DURING TRANSPORT. DID NOT SEE ANYTHING UNUSUAL, OR CRIMINAL OR ILLEGAL IN VEHICLE ON PICK UP.

THE CUSTOMER'S SIGNITURE AT ORIGIN INDICATES AGREEMENT WITH THE HAULER'S ASSESSMENT OF THE CONDITION OF THIS VEHICLE.			E CUSTOMER'S SIGNITURE AT DESTINATION HICLE WAS RECEIVED IN GOOD CONDITION I OVE, THEREBY RELEASING THE CARRIER FIDITIONAL LIABILITY.	EXCEPT AS NOTED
SHIPPER PRINTED	DATE DATE	AT DESTINATION	RECEIVER SIGNITURE RECEIVER PRINTED AND BATICOVA	DATE DATE