



## Crush hazard.

Stay clear of this area.

Follow lockout procedure before servicing.

DOC0723