Lab 2

- 1. Convert Decimal to 8 bit Binary
 - a. $-49 = 1100 \ 1111_2$
 - b. -239 = XXXX XXXX
 - c. $-95 = 1010\ 0001_2$
 - d. -200 = XXXX XXXX
 - e. $-101 = 1001 \ 1011_2$
- 2. Convert to HEX
 - a. 10477 = 28ED
 - b. 23948 = 5D8C
 - c. -33395 = XXXX
 - d. -2000 = F830
 - e. -10101 = D88B
- 3. Convert HEX to Decimal
 - a. DE28 = -8664
 - b. CCC5 = -13115
 - c. 543A = 21562
 - d. 044F = 1103
 - e. F0F0 = -3856
- 4. Convert Decimal to Radix
 - a. $4579 = 10743_8$
 - b. 243 = 3303₄
 - c. $3000 = 18A0_{12}$
 - d. $97 = 241_6$
 - e. $100 = 10201_3$
- 5. Convert
 - a. $A9_{16} = 1010 \ 1001_2$
 - b. $2A6_{16} = 678_{10}$
 - c. $489_{10} = 1E9_{16}$
 - d. $496_{10} = 0100 \ 1001 \ 0110_2$
 - e. $0111\ 0101\ 1000_{BCD} = 758_{10}$
 - f. $1001\ 0101_{BCD} = 0101\ 1111_2$

Lab 3

- 1. Add
 - a. 1001 + 0101 = 01110
 - b. 1100 + 0110 = 10010
 - c. 0011 + 1100 = 01111
 - d. 0101 + 0111 = 01100

- e. 1011 + 0010 = 01101
- 2. Add 4 bit
 - a. 1001 + 0101 = 1110, OF = 0
 - b. 1100 + 0110 = 0010, OF = 0
 - c. 0011 + 1100 = 1111, OF = 0
 - d. 0101 + 0111 = 1100, OF = 0
 - e. 0001 + 1111 = 0000, OF = 1
- 3. Add 8 bit
 - a. 58 + -100 = 1101 0110, OF = 0
 - b. -35 + -69 = 1001 1000, OF = 0
 - c. 89 + 75 = 1010 0100, OF = 1
 - d. -126 + -13 = 0111 0101, OF = 1
 - e. -105 + 80 = 1110 0111, OF = 0
- 4. Convert Decimal to 8 bit to 2's Complement
 - a. 44
- i. 0010 1100
- ii. 1101 0100
- b. 81
- i. 0101 0001
- ii. 1010 1111
- c. 113
 - i. 0111 0001
 - ii. 1000 1111
- d. 62
- i. 0011 1110
- ii. 1100 0010
- e. 125
- i. 0111 1101
- ii. 1000 0011
- 5. Sum Hex
 - a. 6B4 + 3FD = AB2
 - b. A49 + 6BD = 1106
 - c. 7C4 + 3BE = B82
 - d. B69 + 7AD = 1316
- 6. Sum of 12
 - a. 6B4 + 3FE
 - i. AB2₁₆
 - ii. -1358₁₀
 - b. A49 + 6BD
 - i. 106₁₆
 - ii. 262₁₀
 - c. 7C4 + 3BE
 - i. B82₁₆
 - ii. -1150₁₀

- d. B69 + 7AD
 - i. 316₁₆
 - ii. 790₁₀
- 7. Subtraction of HEX
 - a. 6B4 + 3FE
 - i. 2B6
 - ii. 694
 - b. A49 + 6BD
 - i. 38C
 - ii. 908
 - c. 7C4 + 3BE
 - i. 406
 - ii. 1030
 - d. B69 + 7AD
 - i. 3BC
 - ii. 956
- 8. Initials
 - a. M
- i. 77
- ii. 4D
- iii. 0100 1101
- iv. 115
- v. U + 4D
- b. Z
- i. 90
- ii. 5A
- iii. 0101 1010
- iv. 132
- v. U + 5A
- 9. IEEE
 - a. +10.75
 - i. 0
 - ii. 1000 0010
 - iii. 0101 1000 0000 0000 0000 0000
 - b. -76.0625
 - i. 1
 - ii. 1000 0010
 - iii. 0011 0000 0100 0000 0000 0000
- 10. Convert IEEE Hex to Decimal
 - a. 16.75₁₀
 - b. -187, 310 080₁₀