Bus Pirate SeeedStudios Cable	HiZ	1wire	UART	I2C 2wire	SPI 3wire	JTAG	LA
P0- MISO/RX			RX		MISO	TDO	1
P9- CS/TMS			CTS		CS	TMS	0
P8- MOSI/TX		OWD	TX	SDA	MOSI	TDI	3
P7- CLK/RTS			RTS	SCL	SCK	TCK	2
P6- AUX	AUX I/O -PWM -Measures Hz (5Vmax)						4
P5- Vpu	Input Pullup Resistors (0-5V)						
P4- ADC	Analog/Digital converter (6Vmax)						
P3- 5V	5V	5V	5V	5V	5V	5V	
P2- 3V3	3V3	3V3	3V3	3V3	3V3	3V3	
P1 GND	GND	GND	GND	GND	GND	GND	GND
Dan	g e	r o u s	s Pr	o t	o t y	p e s	