	assignment 4
0-1	List down lo error messages code
	404 - Not found Respons states code.
1	100 - loader awailable waiting time out.
2	102 - unloader awailable waiting time out.
3	103 - press unit attiontime out.
5	16 4 - product out waiting time out.
6	12 C - ByPase Roson.
7	107 - motor low speed waiting time out.
8	1 - 8 - Amount is uniocated
q	in a - stoper action waiting time our.
10	a - am duct input warring - ime our.
11	110 - conveyer action waiting time out.
12	106 - Door is opened.
13	111 - repeat cycle end.
14	112 - error flogget.
15	113 - two boards error.
16	114 - Unknown Exton,
17	115 - Next Station error.
18	116 - No hardware deleted.
19	117 - Product Position Error.
20	118 - Boscoge Error