N64 RGB Advanced 3D bracket Installation Guide:

Parts:


Put no longer required screw into small piece to drill a thread in the part.

Remove screw again.

Put small part into designated hole on the N64

Mount RGB kit into bracket and fasten screw while applying some pressure from below to the small part.

Use a multimeter to verify continuity between GND pad on the kit and the marked screw.

Also test the header pins for continuity. Only top left pin and top right pin should have continuity.