## **SECTION C**

## **Weekly Journal**

## **Instruction to Student:**

- 1. On a daily basis, record the specific task that you carried out for that day.
- 2. At the end of every week, describe one task in more details with diagrams or photos attached.

**Week: 19** Date from: 15/7/2024 to 19/7/2024

Department/Section Attached: Assembly Metrology

Day	Tasks Record
Monday	<ul> <li>Modified the tableau dashboard defect colors.</li> <li>Added additional documentation and content explanation.</li> </ul>
Tuesday	Attended MSB Town Hall for FYQ3
Wednesday	Discussed with supervisor on maintenance and upgrading of code
Thursday	Upgraded API with more features
Friday	Created a TIFF file extraction application

			_	□ X	
		TIFF Frame Extr	actor		
		Select TIFF file to ex	tract		
		Choose File			
		Enter frame index (e.g. 1-3	5)		
		Save Frame			
		0.00015: 111			
		© 2024 Firas Hilman			
Assessment on St	udent				
Grading Scheme :					
Grading Scheme : A (Excellent)	- Consisten	tly exhibit qualities beyond	•	ms.	
Grading Scheme : A (Excellent) B+ (Very Good) B (Good)	<ul><li>Consisten</li><li>Exhibit qu</li><li>Exhibit qu</li></ul>	alities above expectation a alities which are considere	and the norms. d necessary to produc		
Grading Scheme : A (Excellent) B+ (Very Good) B (Good) C+ (Good Credit)	<ul><li>Consisten</li><li>Exhibit qu</li><li>Exhibit qu</li><li>Exhibit go</li></ul>	alities above expectation a alities which are considere od qualities which are the	and the norms. d necessary to produc norm.		
Assessment on St Grading Scheme : A (Excellent) B+ (Very Good) B (Good) C+ (Good Credit) C (Credit) D (Pass)	<ul> <li>Consisten</li> <li>Exhibit qu</li> <li>Exhibit qu</li> <li>Exhibit go</li> <li>Exhibit aco</li> </ul>	alities above expectation a alities which are considere od qualities which are the ceptable qualities which ar	and the norms. d necessary to produc norm. e the norm.	ce good quality work.	
Grading Scheme: A (Excellent) B+ (Very Good) B (Good) C+ (Good Credit) C (Credit) D (Pass)	<ul> <li>Consisten</li> <li>Exhibit qu</li> <li>Exhibit go</li> <li>Exhibit ac</li> <li>Exhibit qu</li> </ul>	alities above expectation a alities which are considere od qualities which are the	and the norms.  d necessary to product norm. e the norm. in the norm and unace	ce good quality work.	
Grading Scheme: A (Excellent) B+ (Very Good) B (Good) C+ (Good Credit) C (Credit) D (Pass) F (Fail)	<ul> <li>Consisten</li> <li>Exhibit qu</li> <li>Exhibit go</li> <li>Exhibit ac</li> <li>Exhibit qu</li> </ul>	alities above expectation a alities which are considere od qualities which are the ceptable qualities which ar alities which varies betwee	and the norms.  d necessary to product norm.  e the norm.  In the norm and unact table and are hindrar	ce good quality work.	
Grading Scheme: A (Excellent) B+ (Very Good) G (Good) C+ (Good Credit) C (Credit) O (Pass) F (Fail) Conduct:	- Consisten - Exhibit qu - Exhibit go - Exhibit acc - Exhibit qu - Exhibit qu	alities above expectation a alities which are considere od qualities which are the ceptable qualities which ar alities which varies betwee alities which are not accep	and the norms. d necessary to product norm. e the norm. In the norm and unacc table and are hindrar  * Regular /	ce good quality work. ceptable standard. nces to operations.	
Grading Scheme: A (Excellent) B+ (Very Good) B (Good) C+ (Good Credit) C (Credit) D (Pass) F (Fail)  Conduct:  Performance:	- Consisten - Exhibit qu - Exhibit qu - Exhibit go - Exhibit acc - Exhibit qu - Exhibit qu	alities above expectation a alities which are considere od qualities which are the ceptable qualities which ar alities which varies betwee alities which are not accep	and the norms. d necessary to product norm. e the norm. In the norm and unacc table and are hindrar  * Regular /	ce good quality work. ceptable standard. nces to operations.  / Average / Poor	
Grading Scheme : A (Excellent) B+ (Very Good) B (Good) C+ (Good Credit) C (Credit)	- Consisten - Exhibit qu - Exhibit go - Exhibit acc - Exhibit qu - Exhibit qu	alities above expectation a alities which are considere od qualities which are the ceptable qualities which ar alities which varies betwee alities which are not accep	and the norms. d necessary to product norm. e the norm. In the norm and unacc table and are hindrar  * Regular /	ce good quality work. ceptable standard. nces to operations.  / Average / Poor	

			<i>p</i> 0
Name of Supervisor :	Cli Francish@astronter text.	Signature :	Jan 10
*Delete whichever is not app	licable	Date :	