

## [Technical Notes]

Due to the mismatch Pin define, the onboard M.2 slot is not compatible with following M.2 SSDs. To use the following M.2, please use the M.2 to PCIe adapter.

## PCIe M.2 SSD:

Vendor	Model name	Interface	Length
Toshiba	RC500	PCIe3 x 4	2280
Kioxia	EXCERIA	PCIe3 x 4	2280
Kioxia	EXCERIA G2	PCIe3 x 4	2280
WD	SN750 SE	PCIe4 x 4	2280
WD	SN770	PCIe4 x 4	2280
WD	SN850	PCIe4 x 4	2280
WD	SN850X	PCIe4 x 4	2280
WD	SN580	PCIe4 x 4	2280
ZhiTai	TiPlus5000	PCIe3 x 4	2280
ADATA	Legend 710	PCIe3 x 4	2280
ADATA	Legend 750	PCIe3 x 4	2280
ADATA	Legend 850 LITE	PCIe4 x 4	2280
ADATA	Legend 960 MAX	PCIe4 x 4	2280
Patriot	P300	PCIe3 x 4	2280
SK hynix	P41	PCIe4 x 4	2280
Kingston	NV2	PCIe4 x 4	2280
Samsung	990 Pro	PCIe4 x 4	2280
Lexar	NM620	PCIe3 x 4	2280
Lexar	NM760	PCIe4 x 4	2280
Lexar	NM790	PCIe4 x 4	2280
Lexar	NM710	PCIe4 x 4	2280
Lexar	NM610Pro	PCIe3 x 4	2280
Team	MP44L	PCIe4 x 4	2280