S	D	Command Index 110100b	R/W flag	Function Number	RAW flag	Stuff	Register Address	Stuff	Write Data or Stuff Bits	CRC7	Е
1	1	6	1	3	1	1	17	1	8	7	1