
Patent table contrasts
Calculated material saving (%)
20
15
10
5
0
−5
−10
−15
−20
Weak, non-population evidence
17.5
20.0
22.5
25.0
27.5
30.0
32.5
35.0
Width reduction (%)
Center-perforation task mixtures
Material saving (%)
50
40
30
20
10
0
half-task units = 1
half-task units = 1.2
half-task units = 1.5
half-task units = 2
0.0
0.2
0.4
0.6
0.8
1.0
Share of tasks suitable for half width