

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)

Overview		Client Address			
Client Ref	Camlock	Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG			
Description	Lifting Accessories/Vertical Plate Clamp				
Type Of Inspection	6 Months	Report ID	54064	Page	1/1
		Report ID	34004	1 age	17 1

Equipment Information					
Location	Tackle board bay 3	Inspected At			
I.S.I. Equipment Number	124194287	Stourbridge Turning & Grinding Holdings			
Date Of Manufacture		Rufford Road Stourbridge			
Serial Mark / Number	RC11969	West Midlands			
SWL(s) For The Configuration Examined	1.5 tonne (0 - 20 mm)				

Inspection Report				
A - Defects Requiring Immediate Rectification:	None			
B - Defects Requiring rectification within a specified time period:	None			
C - Other defects:	None			
D - Observations:	None			

General Comments

Serviceable and operationally tested.

Declaration

I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	08/04/2024	
Next Inspection Date	08/10/2024	
Last Inspection Date	Not Known	

John Keber
Surveyor



Industrial Safety Inspections Ltd Tel: 22-23 Amber Business Village Amington Fm:

Amington Tamworth Staffordshire B77 4RP +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com