

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)

| Overview | | Client Address | | | |
|-------------|-----------------------------------------------------|---------------------------------------------------------|-------|------|-----|
| Client Ref | Hyster H3.00 XL | Stourbridge Turning & Grinding Holdings Rufford Road | | | |
| Description | Fork Lift & Pallet Trucks/Counter Balance Fork Lift | Stourbridge West Midlands DY9 7NG | | | |
| Type Of | 6 Months | | | | |
| Inspection | | Report ID | 54068 | Page | 1/2 |

| Equipment Information | | | |
|---------------------------------------|---------------------------------------------|-----------------------------------------|--|
| Location | Works | Inspected At | |
| I.S.I. Equipment Number | 10233514 | Stourbridge Turning & Grinding Holdings | |
| Date Of Manufacture | 1992 | Rufford Road Stourbridge | |
| Serial Mark / Number | C177B14333N | West Midlands | |
| SWL(s) For The Configuration Examined | 2750 kg @ 500 mm ctrs. Maximum Lift 3650 mm | | |

| Inspection Report | |
|---------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|
| A - Defects Requiring Immediate Rectification: | None |
| B - Defects Requiring rectification within a specified time period: | None |
| C - Other defects: | 1) The seat safety / cut out switch is inoperative - to rectify. |
| D - Observations: | The load chains show wear but remain serviceable. 2) The load forks remain serviceable. Slight wewr in tilt ram anchorages but remain serviceable. |

General Comments

Inspection carried out with defects noted

Declaration

I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.



Industrial Safety Inspections Ltd Tel: +44 (0) 1675 481779 22-23 Amber Business Village Amington Email: info@isisafety.com

Web: www.isisafety.com

Tamworth Staffordshire B77 4RP



REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)

| Overview | | Client Address | | | |
|------------------|-----------------------------------------------------|----------------------------------------------------------------------------------------------------|------|-----|--|
| Client Ref | Hyster H3.00 XL | Stourbridge Turning & Grinding Holdings Rufford Road Stourbridge West Midlands DY9 7NG | | | |
| Description | Fork Lift & Pallet Trucks/Counter Balance Fork Lift | | | | |
| Type Of 6 Months | | | | | |
| Inspection | Report ID | 54068 | Page | 2/2 | |

| Report Date | 08/04/2024 |
|----------------------|------------|
| Next Inspection Date | 08/10/2024 |
| Last Inspection Date | 24/11/2023 |



| John Keber | Λl |
|------------|----|
| Surveyor | MM |

Industrial Safety Inspections Ltd Tel: 22-23 Amber Business Village

Amington Tamworth Staffordshire B77 4RP +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com