

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



As required by the Lifting Operations and Lifting Equipment Regulations (Regulation 9)

Overview			Client Address					
Client Ref	Chain Mail sling			Stourbridge Turning & Grinding Holdings Rufford Road				
Description	Lifting Accessories/Chain Sling			Stourbridge West Midlands DY9 7NG				
Type Of 6 Months								
Inspection				Report ID	54065	Page	1/1	
Equipment Info	ormation							
Location			Tackle board bay 3	Inspected At				
I.S.I. Equipment Number			10233509	Stourbridge Turning & Grinding Holdings				
Date Of Manufacture				Rufford Road Stourbridge				
Serial Mark / Number			OTC7495M	West Midlands				
SWL(s) For The Configuration Examined			2 ton					
Inspection Report								
A - Defects Requiring Immediate Rectification:		None						
B - Defects Requiring rectification within a specified time period:		None						
C - Other defects:		None						
D - Observations:		None						

\sim		\sim		4
Liar	Iorai	I om	man	11.
OG I	петат	Com		

Serviceable

Declaration

I confirm that the equipment was, thoroughly examined on the 08/04/2024 and subject to any remedial action(s) noted in section A being completed, is safe to operate.

Report Date	08/04/2024
Next Inspection Date	08/10/2024
Last Inspection Date	24/11/2023

John Keber
Surveyor



Industrial Safety Inspections Ltd Tel: 22-23 Amber Business Village

Amington Tamworth Staffordshire B77 4RP +44 (0) 1675 481779

Email: info@isisafety.com Web: www.isisafety.com