Materials that I need

1. water pH sensor kit| status: not exist.



2. DS18b20 water temperature sensor status: not exist

Role: you precisely measure temperatures in wet environments



3. TDS meter analogue sensor |status: not exist

Role: For measuring TDS value and to reflect the cleanliness of the water vegetables should have around 900-1000 ppm.

