



Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 5

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

 Sketch: Lines, Circles, Centerlines, Polygons, Sketch Fillets

• Features: Sweeps









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


o The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines, Sketch Fillets

• Features: Sweeps









Sweep Boss/Cut (Level 8)

Units: IPS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Centerlines, Arcs
- Features: Revolves, Sweeps, Fillets and Chamfers

HINT: Extend sweep into sphere.









Sweep Boss/Cut (Level 8)

Units: IPS

Difficulty Level: MediumCertification: CSWA

• Duration (min): 20

Design Intent:

 The part's origin location is indicated in red.


o The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines

Features: Sweeps, Extrude CutPatterns: Mirror









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 40

• Design Intent:

 The part's origin location is indicated in red.

• The part is asymmetric.

All sketches are fully defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines

• Features: Lofts, Extrude Boss, Extrude Cut

Patterns: Circular

HINT: The loft is between two circles.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWA

Duration (min): 5

Design Intent:

 The part's origin location is indicated in red.

• The part is symmetric.


o All sketches are fully defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Arcs

Features: Sweeps

HINT: The Sweep can use the Circular Profile option.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: MediumCertification: CSWA

Duration (min): 20Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


All sketches are fully defined.

Suggested Sketch Tools / Features

• Sketch: Lines, Arcs, Centerlines, Slots, Trim

Features: Extrude Boss, Sweeps, Fillets and Chamfers

Patterns: Mirror









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully defined.

Suggested Sketch Tools / Features

- Sketch: Lines, Circles, Centerlines, Arcs, Rectangles, Sketch Fillets
- Features: Lofts, Extrude Boss, Extrude Cut
- Reference Geometry: Planes

HINT: Loft between a square sketch and a planar face.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: MediumCertification: CSWA

Duration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully defined.


Suggested Sketch Tools / Features

• Sketch: Lines, Circles, Centerlines

• Features: Lofts, Extrude Boss, Extrude Cut

Reference Geometry: Planes

HINT: The cap is lofted.









Sweep Boss/Cut (Level 8)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

- The part's origin location is indicated in red.
- The part is symmetric.
- o All sketches are fully-defined.
- o All fillets on the path are equal.

Suggested Sketch Tools / Features

• Sketch: Lines, Centerlines, Circles

• Features: Sweeps

• Reference Geometry: Planes

