



#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully-defined.

#### **Suggested Sketch Tools / Features**

Sketch: Lines, Circles, CenterlinesFeatures: Revolves, Extrude Cut

Patterns: Circular









#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

o The part is asymmetric.

All sketches are fully-defined.

#### **Suggested Sketch Tools / Features**


• Sketch: Lines, Circles, Centerlines

Features: Extrude Boss, Revolves, Fillets and Chamfers

Patterns: Linear

Reference Geometry: Planes

HINT: Skip instances in the Linear Pattern.









#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


• The part is symmetric.

All sketches are fully-defined.

### **Suggested Sketch Tools / Features**

Sketch: Lines, Arcs, CenterlinesFeatures: Extrude Boss, Revolves

Patterns: Linear









### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

#### **Suggested Sketch Tools / Features**

• Sketch: Lines, Circles, Centerlines, Arcs

Features: RevolvesPatterns: Circular









#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: EasyCertification: CSWADuration (min): 10

Design Intent:

 The part's origin location is indicated in red.

The part is axisymmetric.

All sketches are fully-defined.

### **Suggested Sketch Tools / Features**


• Sketch: Lines, Circles, Centerlines, Rectangles

• Features: Extrude Boss, Extrude Cut

Patterns: Circular, Mirror

Reference Geometry: Planes

HINT: The holes and cuts are patterned.









#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: MediumCertification: CSWADuration (min): 15

Design Intent:

 The part's origin location is indicated in red.


The part is symmetric.

All sketches are fully-defined.

#### **Suggested Sketch Tools / Features**

- Sketch: Lines, Circles, Rectangles, Offset, Slots, Centerlines
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers
- Patterns: Linear

HINT: Thickness remains the same.









#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 30

Design Intent:

 The part's origin location is indicated in red.

o The part is axisymmetric.

All sketches are fully-defined.


#### **Suggested Sketch Tools / Features**

• Sketch: Lines, Circles, Centerlines

Features: Extrude Boss, Revolves, Fillets and Chamfers

· Patterns: Circular

HINT: All 4 blades are evenly spaced.









### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 25

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.


o All sketches are fully-defined.

### **Suggested Sketch Tools / Features**

• Sketch: Lines, Circles, Centerlines, Slots

Features: Extrude Boss, Extrude Cut

Patterns: Linear, Mirror










#### Feature Patterning (Level 7)

- Units: MMGS
- Difficulty Level: HardCertification: CSWADuration (min): 35
- Design Intent:
  - The part's origin location is indicated in red.
  - The part is symmetric.
  - All sketches are fully-defined.

#### **Suggested Sketch Tools / Features**

- Sketch: Lines, Circles, Centerlines, Rectangles
- Features: Extrude Boss, Extrude Cut, Fillets and Chamfers
- Patterns: Mirror









#### Feature Patterning (Level 7)

Units: MMGS

Difficulty Level: HardCertification: CSWADuration (min): 45

Design Intent:

 The part's origin location is indicated in red.

The part is symmetric.

All sketches are fully-defined.

#### **Suggested Sketch Tools / Features**

• Sketch: Lines, Circles, Centerlines, ARcs

 Features: Extrude Boss, Extrude Cut, Revolves, Fillets and Chamfers

Patterns: Mirror

