

Product Information

Date: June 18th 2013

Product: EVO192 (192-Zone Control Panel)

SP4000/65/5500/6000/7000 (Spectra 32-Zone Control Panels)

MG5000/5050 (MAGELLAN 32-Zone Wireless Transceiver Control Panel)

PCS250 (GPRS/GSM Communicator Module)

Subject: New EVO192 firmware version 2.75 release

New SP5500/6000/7000 firmware version 4.94 release

New MG5000/5050 firmware version 4.74 release

New SP4000/65 firmware version 5.14 release

New PCS250 firmware version 1.24 release

Downloads: To download firmware V4.94 (SP5500), *click here

To download firmware V4.94 (SP6000), *click here To download firmware V4.94 (SP7000), *click here

To download firmware V4.74 (MG5000), *click here To download firmware V4.74 (MG5050), *click here

To download firmware V5.14 (SP4000), *click here To download firmware V5.14 (SP65), *click here

To download firmware V2.75 (EVO192), *click here

To download firmware V1.24 (PCS250), *click here

To download the firmware upgrade instructions, <u>click here</u> *requires login name and password to download

Resolved Issues: Communication issue with PCS250

We have discovered a communication issue between the panels and the PCS250 that could cause the PCS250 to lose connection to the cell phone network. This can also present itself as the VDMP3 being displayed as missing in the Trouble list

Network connectivity (PCS250 only)

On certain networks the PCS250 was having issues with connecting to the mobile network, both during initial setup and if the network was lost.

Contact: If you require any additional information or if you have any questions, please do

not hesitate to contact our Distributor support department.

Email: distributorsupport@paradox.com

Phone: +1. 450.491.7444

Paradox Security Systems LTD- Product Information #SP-EVO-PCS250-13-06-18