Purpose	Action	Behavior	Return
Run Solvent Leak Test		1 Run Solvent Leak Test	T/F (Leak Test Passed)





*for diagnostic utility: x is an arbitrary percentage, for start of job, x is minimum solvent required by job

uns