
Adding a Delay to a Power Meter Alarm

(This image is from Station / CentralController / Points / PowerMeter / PowerMetern)



This may have been a knee-jerk response to a different problem.

On 2019.11.21 I discovered that at H&M 363 the power meter alarm delay was not linked for L2 and L3. It was fixed in the template sometime after H&M 363 was programmed.