

SPECK Installation Guide

Substrate Point Enumeration and Classification Kit — install, launch, and uninstall on Windows and macOS.

WINDOWS

Install_SPECK.bat • SPECK.bat • Uninstall_SPECK.bat

Before you start

You'll need Windows 10 or 11 and an internet connection for the first install. Nothing else has to be installed ahead of time — everything else (Python, PyQt6, and the rest) is installed automatically.

Install

1 Download the ZIP

Go to the SPECK GitHub page below, click the green **Code** button, then **Download ZIP**. It'll land in your Downloads folder as `SPECK-main.zip`.

```
https://github.com/bransond-sms/SPECK
```

2 Extract it

Right-click the downloaded ZIP and choose **Extract All**, then pick wherever you want the launch icon to appear — for example your Desktop. The shortcut is created one level up from the extracted SPECK folder.

3 Run the installer

Open the extracted **SPECK** folder and double-click **Install_SPECK.bat**.

4 Let it set things up

The installer detects an existing Conda/Miniforge install, or silently installs Miniforge if none is found. It then creates (or updates) the `speck` conda environment from `environment.yml`, and creates a **SPECK** shortcut next to the SPECK folder.

5 Launch

Double-click the new **SPECK** shortcut (or run `SPECK.bat` directly from inside the folder).

Getting updates

When Branson sends a new version, download the new ZIP, extract it over the same folder, and re-run `Install_SPECK.bat` — it updates the existing environment in place rather than reinstalling from scratch.

Uninstall

1 Run the uninstaller

Double-click **Uninstall_SPECK.bat** inside the SPECK folder.

2 Automatic cleanup

It removes the speck conda environment and the SPECK shortcut without asking.

3 Miniforge (only if it asks)

If Miniforge was installed by SPECK's own installer, you'll be asked whether to remove it entirely too. If you already had Conda/Miniforge before installing SPECK, it's left alone automatically — removing it could break other software you use.

4 Delete the folder yourself

The SPECK folder itself — including any saved .speck sessions or CSV exports — is left untouched. Back up anything you want to keep, then delete the folder manually.

Seeing “The syntax of the command is incorrect”?

That usually means the installer was run from inside the still-compressed ZIP instead of the extracted folder. Right-click the ZIP → **Extract All** first, then run everything from inside the extracted SPECK folder.

macOS

Install_SPECK.command • SPECK.command • Uninstall_SPECK.command

Before you start

You'll need a Mac (Apple Silicon or Intel — the installer detects your chip automatically) and an internet connection for the first install.

Install

1 Download the ZIP

Go to the SPECK GitHub page below, click the green **Code** button, then **Download ZIP**. It'll land in your Downloads folder.

```
https://github.com/bransond-sms/SPECK
```

2 Extract it

Double-click the downloaded ZIP in Downloads to unzip it — this creates a SPECK-main folder. Move that folder to wherever you want the launch shortcut to appear (e.g. your Desktop); renaming it to just “SPECK” is optional but tidier.

3 Run the installer

Open the folder and double-click **Install_SPECK.command**. The first time, macOS will likely warn that it's from an unidentified developer since it came from the internet — right-click the file and choose **Open** instead of double-clicking to get past that. A Terminal window will then open and walk through the setup.

4 Let it set things up

It detects an existing Conda/Miniforge install, or downloads and silently installs Miniforge built for your Mac's chip. It then creates (or updates) the speck conda environment, and creates a **SPECK.command** shortcut next to the SPECK folder.

5 Launch

Double-click the new **SPECK.command** shortcut.

Still won't open, or double-clicking does nothing?

Open Terminal, drag the SPECK folder onto the Terminal window to fill in its path, then run the two lines below (adjust the file name for Uninstall if needed):

```
chmod +x Install_SPECK.command
./Install_SPECK.command
```

Uninstall

1 Run the uninstaller

Double-click **Uninstall_SPECK.command** inside the SPECK folder (right-click → **Open** first time, same as the installer).

2 Automatic cleanup

It removes the speck conda environment and the `SPECK.command` shortcut without asking.

3 Miniforge (only if it asks)

If Miniforge was installed by SPECK's own installer, you'll be asked whether to remove it entirely too. If you already had Conda/Miniforge before installing SPECK, it's left alone automatically.

4 Delete the folder yourself

The SPECK folder itself — including any saved `.speck` sessions or CSV exports — is left untouched. Back up anything you want to keep, then delete the folder manually.

Quick reference

	WINDOWS	macOS
Install	Install_SPECK.bat	Install_SPECK.command
Launch	SPECK.bat / SPECK shortcut	SPECK.command shortcut
Uninstall	Uninstall_SPECK.bat	Uninstall_SPECK.command

Need help?

Both platforms' scripts print clear error messages when something goes wrong. If you hit one that isn't covered above, copy the full message from the window and send it to Branson.