Laminectomy Only

Threshold = 0.01

Threshold = 0.015

Threshold = 0.02

Threshold = 0.025

Cumulative % of total cord volume above MPS threshold

MPS concentration effective radius r (mm)

P3 (Normal)
P7 (Normal, fused)
P10 (Normal)
P11 (Normal)
P2 (Residual compression)
P4 (Residual compression)
P9 (Residual compression)
P1 (S-curve, fused)
P5 (S-curve, fused)
P6 (S-curve)
P8 (S-curve, fused)
P12 (S-curve)
Flexion
Extension