


## SENSOR TERMINALS




All resistors are 1/4W unless otherwise specified.

Keep Analog and Digital grounds seperately.


IC22 requires proper heatsink.

SW1 - SW20 : Trigger point setup switches. Activate only one switch in a group.


J1 : Use 12V - 15V 1.5A DC Power Supply.







SENSOR AMPLIFIER AND LEVEL DETECTOR



THIS SYSTEM IS A PART OF COCA'S EMERGE + TECH PROJECT.