

High side without internal Dead time. MCU has to provide it. No overshoot protection here.