-pass Instruction value down pipeline to make it easier to determine rs1, rs2, rd hazard detection

