

B-INFOHUB BRIDGE v1.0

Bridge & Station GC-1032 -> Home Assistant

2026-08 presented

CONTROLLER: SLAVE 10 9600 BERT

measured on the null, NOT the common default of 1 \ 19500

11 13V DC ONLY - NEVER 5V+G

12 to ABC controller A and B only (trans GND lands on 11).

2wop V/B if the bus stays silent - it cannot damage anything.

12 to InfoHub: +13V (used by 15, 25), GND, A, B

11 13V feeds the bridge, 12 2V feeds the InfoHub - separate on pinpos:

the InfoHub cell modem buses hard and must not take the telemetry down.

PORT A (12) controller 1013 DI \ 1016 RO \ 1014 DE+RE

PORT B (14) InfoHub 1025 DI \ 1028 RO \ 1021 DE+RE

191\192 = 1508 termination. LEAVE OFF unless you see CRC errors:

9600 baud proved reliable UNTERMINATED, 208\268 reads, 2026-08-27.

EB23-DeVHC-25, or -25U if you need an external antenna